



General information

Make	FORD
Model	C-MAX ZETEC 100
Colour	Silver
Year of manufacture	2010
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 3

Date	2023-04-06
Pictures	26
Listing price	View report



source: cargurus.co.uk

Entry 2

Date	2022-01-18
Pictures	21
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-12-05
Pictures	22
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-07
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	10
Total items failed	5

MOT #17	2023-11-28 09:29
MOT test number	263966876669
Result	✓ Passed
Next expiry date	2024-12-07

MOT #16	2023-11-28 09:29
MOT test number	669327506422
Result	✗ Failed
Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #15	2022-11-28 10:42
MOT test number	959180174428
Result	✓ Passed

MOT #14	2021-12-08 11:54
MOT test number	533489042019
Result	✓ Passed

MOT #13	2021-11-29 09:54
MOT test number	663325529960
Result	✓ Passed

**MOT #12**

2021-06-21 15:23

MOT test number

193729341575

Result

✓ Passed

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement
suspension rear lower link arm bushes worn (5.3.4 (a) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Power steering component has slight seepage from a component (2.1.5 (a))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement
suspension rear lower link arm bushes worn (5.3.4 (a) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #11

2020-06-24 11:44

MOT test number

871461742594

Result

✓ Passed

MOT #10

2019-06-19 10:22

MOT test number

255490414176

Result

✓ Passed

MOT #9

2018-06-07 13:59

MOT test number

595903464683

Result

✓ Passed



MOT #8	2017-06-05 11:05
---------------	------------------

MOT test number	369076313158
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2016-06-22 10:26
---------------	------------------

MOT test number	462597231526
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2016-06-22 10:26
---------------	------------------

MOT test number	121716699826
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)
--------------------------------	--

MOT #5	2015-06-25 11:45
---------------	------------------

MOT test number	266316375445
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2014-06-12 10:31
---------------	------------------

MOT test number	235783964193
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2013-07-03 15:23
---------------	------------------

MOT test number	259224183116
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2013-03-28 11:51
---------------	------------------

MOT test number	988977883041
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #1	2013-03-28 11:51
MOT test number	138287083048
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too high (1.8)
Pass with rectification	Nearside Headlamp not working on dipped beam (1.7.5a)
Pass with rectification	Offside Headlamp aim too high (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
7 December 2024

Tax status	Valid until 1 April
Days left	338
MOT expiry date	7 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-05-20
Last registration	2023-11-28
Complete history	See info



Registration #1	2010-05-20	17 mi
Registration #2	2013-03-28	33.995 mi
Registration #3	2013-07-03	36.480 mi
Registration #4	2014-06-12	42.823 mi
Registration #5	2015-06-25	48.656 mi
Registration #6	2016-06-22	52.413 mi
Registration #7	2016-06-22	52.413 mi
Registration #8	2017-06-05	55.096 mi
Registration #9	2018-06-07	58.045 mi
Registration #10	2019-06-19	61.158 mi
Registration #11	2020-06-22	64.271 mi
Registration #12	2021-06-22	67.384 mi
Registration #13	2022-06-22	70.497 mi
Registration #14	2023-06-22	73.610 mi
Registration #15	2024-06-22	76.723 mi
Registration #16	2025-06-22	79.836 mi
Registration #17	2026-06-22	82.949 mi
Registration #18	2027-06-22	86.062 mi
Registration #19	2028-06-22	89.175 mi
Registration #20	2029-06-22	92.288 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1372 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AL38072