





General information

Make	PEUGEOT
Model	HORIZON BLUE HDI S/S TEPEE ALLURE
Colour	Silver
Year of manufacture	2016
Top speed	101 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	В





Internet history

Entry 1

Date

Pictures

2021-06-25

28

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-08
MOT pass rate	55 %
MOT passed	6
Failed MOT tests	5
Total advice items	14
Total items failed	10

MOT #11	2024-03-06 16:06	
MOT test number	545493600297	
Result	🗸 Passed	
Next expiry date	2025-03-08	
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))		

MOT LEST HUMBEL	мот	test	number
-----------------	-----	------	--------

Result	×	Failed
Fail	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Minor (4.7.1 (b)	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources) (i))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

2024-03-06 13:23

910268391203





МОТ #9	2023	3-03-07 14:54
MOT test number	30	63309138725
Result		🗸 Passed
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
МОТ #8	2023	3-03-07 14:54
MOT test number	7:	14855764421
Result		🗙 Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7	2022-03-07 16:45
MOT test	number 703306924158
Result	✓ Passed
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

МОТ #6	2021-02-25 14:47
MOT test number	755516011551
Result	✓ Passed
MOT #5	2021-02-25 11:27
MOT test number	726959851295
Result	🗙 Failed
Fail Emissions not tested (8.2.2.2 (e))	

 Fail
 Offside Rear Passenger's seat insecure (6.2.6 (a) (ii))





MOT #4	2020-03-09 11:50	
MOT test number	659528985742	
Result	✓ Passed	
MOT #3	2020-03-09 11:41	
MOT test number	358414245208	
Result	🗙 Failed	
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))		
Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))		
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		

MOT #2	2019-04-18 10:15
MOT test number	406944322653
Result	✓ Passed
Advice Engine covers and under shields fitted covering some items	

MOT #1		2019-04-18 10:15
MOT test number		185475389118
Result		🗙 Failed
Pass with rectification	Nearside Front Headlamp aim too high (4.1.2 (a))	
Advice Engine covers and under shields fitted covering some items		
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))	



Tax & MOT check

✓ Taxed Tax due: 1 July 2024	✓ MOT Expires: 8 March 2025
Tax status	Valid until 1 July
Days left	63
MOT expiry date	8 March 2025
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. DEM PE
Туре	
Damage 2	Annet
Date	No. Contraction of the second
Category	AMP
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2016-06-08
Last registration	2024-03-06
Complete history	See info



Registration #1	2016-06-08	9 mi
Registration #2	2019-04-18	11.531 mi
Registration #3	2019-04-18	11.531 mi
Registration #4	2020-03-09	15.129 mi
Registration #5	2020-03-09	15.129 mi
Registration #6	2021-02-25	16.363 mi
Registration #7	2021-02-25	16.363 mi
Registration #8		11.777 esi
Registration #9		11.777 esi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.117 mi

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
50566	
S0567	
S0569	

Safety ratings

Number of axles CarCheck.co.uk

NCAP rating	****
Adult	73%
Children	78%
Pedestrian	48%
Safety systems	86%
Overall rating	70%
Video	see crash video



Dimensions & weight	
Width	2112 mm
Height	1862 mm
Length	4384 mm
Wheel base	2728 mm
Max. allowed weight	2060 kg
Additional information	
Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

2

Engine number

JBHB3076096