



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 SPORT HDI
Colour	Black
Year of manufacture	2007
Top speed	117 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-10-04
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-15
MOT pass rate	63 %
MOT passed	15
Failed MOT tests	9
Total advice items	101
Total items failed	10

MOT #24	2024-02-12 13:13
MOT test number	305195794876
Result	✓ Passed
Next expiry date	2025-02-15
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #23	2023-02-16 16:59
MOT test number	226506000195
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #22**

2023-02-15 18:03

MOT test number

262009232633

Result**✗ Failed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #21**

2022-02-09 17:05

MOT test number

457251990185

Result**✓ Passed****Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #20**

2022-02-09 13:10

MOT test number

640350240505

Result**✗ Failed****Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))



MOT #19

2021-03-09 16:59

MOT test number

790869700565

Result

✓ Passed

- Minor

Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice

Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm - worn on outer (5.2.3 (e))
- Advice

O/s/f tyre worn on outer
- Advice

O/s/f wishbone rear bush deteriorated
- Minor

Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice

Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice

Play in steering rack inner joint(s)
- Advice

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice

N/s/f wishbone rear bush deteriorated

**MOT #18**

2021-03-09 15:00

MOT test number

429083337700

Result**✗ Failed**

- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Play in steering rack inner joint(s)
- Advice** N/s/f wishbone rear bush deteriorated
- MAJOR** Offside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm - worn on outer (5.2.3 (e))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** O/s/f tyre worn on outer
- Advice** O/s/f wishbone rear bush deteriorated
- MAJOR** Nearside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))
- MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #17

2020-02-28 14:13

MOT test number

912895641636

Result**✓ Passed**

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside Play in steering rack inner joint(s)
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

**MOT #16**

2020-02-25 12:20

MOT test number

253909514194

Result**✗ Failed****MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Play in steering rack inner joint(s)**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge badly worn on inside edge close to limit and cracking in treads (5.2.3 (e))**MAJOR** Offside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**DANGEROUS** Nearside Rear Tyre has ply or cords exposed cracked to cords and badly worn below limit on inside edge (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing on outside edge (5.2.3 (e))**MOT #15**

2019-03-07 16:01

MOT test number

804628182922

Result**✓ Passed****Advice** Head lights starting to go opaque**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Brake pad(s) wearing thin rears (1.1.13 (a) (ii))**Advice** Shock absorbers has a slightly worn bush o/s and n/s lowers (5.3.2 (c))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Suspension arm pin or bush worn but not resulting in excessive movement lower arm bush (5.3.4 (a) (i))

**MOT #14**

2019-03-06 13:45

MOT test number

543220159209

Result**✗ Failed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Rear Position lamp not working (4.2.1 (a))
- Advice** Offside Suspension arm pin or bush worn but not resulting in excessive movement lower arm bush (5.3.4 (a) (i))
- DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Shock absorbers has a slightly worn bush o/s and n/s lowers (5.3.2 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Head lights starting to go opaque
- Advice** Brake pad(s) wearing thin rears (1.1.13 (a) (ii))
- MAJOR** Rear fog lamp not working (4.5.1 (a) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13

2018-03-07 16:39

MOT test number

827593747417

Result**✓ Passed**

- Advice** Offside & Nearside rear tyres wearing on inner edges
- Advice** Nearside Play in steering rack inner joint(s)

**MOT #12** 2018-03-07 13:42**MOT test number** 675451053143**Result** ✗ Failed**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside & Nearside rear tyres wearing on inner edges**Advice** Nearside Play in steering rack inner joint(s)**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)**MOT #11** 2017-02-17 15:46**MOT test number** 651529324595**Result** ✓ Passed**Advice** N/s/r shock absorber dust cover insecure**MOT #10** 2017-02-17 11:39**MOT test number** 416250792286**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** N/s/r shock absorber dust cover insecure**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)

**MOT #9** 2016-03-07 13:48**MOT test number** 771520317861**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** O/s and n/s/r shocker bushes starting to split**MOT #8** 2016-03-07 09:57**MOT test number** 468928852684**Result** ✗ Failed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** O/s and n/s/r shocker bushes starting to split**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #7** 2015-03-10 11:26**MOT test number** 717319065034**Result** ✓ Passed**Notice** Rear wiper split**Notice** Both front tyres worn on the edges**Notice** Passenger door damaged**Notice** Offside lower suspension arm bush starting to split**MOT #6** 2014-03-11 13:14**MOT test number** 357290374068**Result** ✓ Passed**Notice** Front tyres wearing thin**Notice** Under-trays fitted obscuring some underside components

**MOT #5** 2014-03-11 11:00**MOT test number** 407010974051**Result** ✗ Failed**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Notice** Under-trays fitted obscuring some underside components**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Notice** Front tyres wearing thin**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**MOT #4** 2013-03-08 15:17**MOT test number** 689547363069**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2012-03-02 10:46**MOT test number** 165092362039**Result** ✓ Passed**Notice** Nearside front tyre down to wear bar indicators**MOT #2** 2011-03-08 14:16**MOT test number** 817367661029**Result** ✓ Passed**MOT #1** 2010-03-06 12:23**MOT test number** 760875960042**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
15 February 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	15 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history


Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2007-03-13
Last registration	2024-02-12
Complete history	See info



Registration #1	2007-03-13	6 mi
Registration #2	2010-03-06	31.090 mi
Registration #3	2011-03-08	37.367 mi
Registration #4	2012-03-02	43.146 mi
Registration #5	2013-03-08	56.400 mi
Registration #6	2014-03-11	68.190 mi
Registration #7	2014-03-11	68.190 mi
Registration #8	2015-03-10	77.835 mi
Registration #9	2016-03-07	86.940 mi
Registration #10	2016-03-07	86.940 mi
Registration #11	2017-02-17	99.410 mi
Registration #12	2017-02-17	99.410 mi
Registration #13	2018-03-07	112.130 mi
Registration #14	2019-03-07	112.130 mi
Registration #15	2019-03-07	112.130 mi
Registration #16	2019-03-07	112.130 mi
Registration #17	2019-03-07	112.130 mi
Registration #18	2019-03-07	112.130 mi
Registration #19	2019-03-07	112.130 mi
Registration #20	2019-03-07	112.130 mi
Registration #21	2019-03-07	112.130 mi
Registration #22	2019-03-07	112.130 mi
Registration #23	2019-03-07	112.130 mi
Registration #24	2019-03-07	112.130 mi
Registration #25	2019-03-07	112.130 mi
Registration #26	2019-03-07	112.130 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1530 mm
Length	4211 mm
Wheel base	2608 mm
Kerb weight	1335 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	JB893025088