





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CC GT TDI BLUEMOTION TECHNOLOGY DSG
Colour	White
Year of manufacture	2015
Top speed	132 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	60.1 mpg
Consumption combined	53.3 mpg
CO2 emission	131 g/km
CO2 label	E



CarCheck.co.uk page 1/12



SM15KFD report date: 2024-03-28

Internet history

Entry 1

Date	2021-02-06	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

CarCheck.co.uk page 2/12



SM15KFD report date: 2024-03-28

MOT history

MOT expiry date	2024-09-28
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	26
Total items failed	1

MOT #7	2023-09-13 08:27	
MOT test number	583330651091	
Result	✓ Passed	
Next expiry date	2024-09-28	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))		
Advice Nearside Rear Nail in tyre		

MOT #6		2022-09-29 14:51
MOT test	number	741989775528
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Nail in tyre	
Advice	Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))	
Advice	Rear Lower Suspension arm corroded but not seriously weakened Both (5.3.3	(b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Corroded	(1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #5 2021-06-30 12:30

MOT test number 891573507931

Result ✓ Passed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4 2020-06-25 12:33

MOT test number 104877641237

Advice Offside Front Suspension component pin or bush slightly worn Rear bush (5.3.4 (a) (i))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Suspension component pin or bush slightly worn Rear bush (5.3.4 (a) (i))

Advice Child Seat fitted not allowing full inspection of adult belt

MOT #3 2019-04-25 13:49

MOT test number 916430686393

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

2019-04-25 11:50 **MOT #2** 121237564270 **MOT** test number Result × Failed **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #1	2018-06-20 17:48
MOT test number	286769873596
Result	√ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	28 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this VOLKSWAGEN had different number plates.	· · · · · · · · · · · · · · · · · · ·	
Plate changes See in this check if this VOLKSWAGEN had different number plates.	VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow	
Plate changes See in this check if this VOLKSWAGEN had different number plates.	***************************************	
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
See in this check if this VOLKSWAGEN had different number plates.		More info >
	Plate changes	
Plate since	See in this check if this VOLKSWAGEN had different number plates.	
Plate since	Number of plates	
UK UK	Current registration	UK UK
	Plate since	
Plate since	Current registration	UK UK
	Plate since	

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-06-05
Last registration	2023-09-13
Complete history	See info



Registration #1	2015-06-05	17 mi
Registration #2	2018-06-20	12.316 mi
Registration #3	2019-04-25	30.059 mi
Registration #4	2019-04-25	30.068 mi
Registration #5	2020-06-25	38.898 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 11/12



SM15KFD report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	85%
Children	87%
Pedestrian	66%
Safety systems	76%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	2090 mm
Height	1421 mm
Length	4902 mm
Wheel base	2710 mm
Kerb weight	1564 kg
Max. allowed weight	2070 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	4
CarChack so uk	nago 12/1:

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	CFFBL40298