





report date: 2024-03-28

General information

Make	RENAULT
Model	SCENIC DYNAMIQUE TOMTOM ENERGY DCI S/S
Colour	Grey
Year of manufacture	2013
Top speed	112 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/12




Internet history

Entry 1

Date 2021-08-07

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

Advice

MOT expiry date	2024-08-22
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	12
Total items failed	5

MOT #11	2023-08-22 06:19	
MOT test number	962452248459	
Result	✓ Passed	
Next expiry date	2024-08-22	
Advice Brake pad(s) wearing thin FRONT AND REAR PADS WOR CUSTOMER ADVISED (1.1.13 (a) (ii))		

MOT #10	2022-08-09 11:46
MOT test number	941178969022
Result	√ Passed

MOT #9	2022-08-08 13:29
MOT test number	247922563295

Result × Failed

Advice Rear Brake disc worn, but not excessively Rear discs wearing thin/lipped (1.1.14 (a) (i))

Rear Brake pad(s) wearing thin Rear pads wearing low (1.1.13 (a) (ii))

Advice Front Tyre slightly damaged/cracking or perishing Tyre perishing/cracking in radial grooves (5.2.3 (d) (ii))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt NSF Outer CV boot insecure on outer clip and released all grease (6.1.7 (g) (ii))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated CV boot Perishing and weeping grease (6.1.7 (g) (i))

CarCheck.co.uk page 3/12



MOT #8 2022-07-25 10:06

MOT test number 194414359918

Result X Failed

Fail Offside Rear Seat belt buckle not functioning as intended Seat belt buckle fitted to incorrect side of seat making it unable to hold a passenger (7.1.2 (d))

Advice Rear Brake pad(s) wearing thin Rear pads wearing low (1.1.13 (a) (ii))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Rear Seat belt buckle not functioning as intended Seat belt buckle fitted to incorrect side of seat making it unable to hold a passenger (7.1.2 (d))

Advice Front Tyre slightly damaged/cracking or perishing Tyre perishing/cracking in radial grooves (5.2.3 (d) (ii))

Advice Rear Brake disc worn, but not excessively Rear discs wearing thin/lipped (1.1.14 (a) (i))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #7 2021-08-23 13:13

MOT test number 584197081511

Result \square Passed

MOT #6 2020-10-07 12:39

MOT test number 969276550034

Result

Passed

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2019-10-01 12:52

MOT test number 136956433628

Result \(\sqrt{Passed} \)

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



MOT #4	2018-10-04 15:41
MOT test number	607341796465
Result	✓ Passed
MOT #3	2017-10-14 13:27
MOT test number	736131827402
Result	✓ Passed
MOT #2	2016-10-17 13:43
MOT test number	907526237962
Result	✓ Passed
MOT #1	2016-09-20 10:26
MOT test number	468631189275
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	22 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner	history
OWITCE	iliotoi y

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

2000000	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	NE UK
Plate since	
Current registration	UK UK
Flate since	m-0-0
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-10-11
Last registration	2023-08-22
Complete history	See info



Registration #1	2013-10-11	14 mi
Registration #2	2016-09-20	18.855 mi
Registration #3	2016-10-17	19.517 mi
Registration #4	2017-10-14	22.152 mi
Registration #5	2018-10-04	24.194 mi
Registration #6	2019-10-01	25.732 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditionin
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1845 mm
Height	1640 mm
Length	4366 mm
Wheel base	2702 mm
Kerb weight	1434 kg
Max. allowed weight	1967 kg

Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number D208373