



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	MODUS DYNAMIQUE DCI 80
Colour	Silver
Year of manufacture	-
Top speed	104 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	185 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-15
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #25	2022-07-07 15:16
MOT test number	317061527882
Result	✓ Passed
Next expiry date	2023-07-12
Advice	Offside Front Strut top bearing noisy
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #24	2022-07-06 11:34
MOT test number	519466741843
Result	✗ Failed
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
MAJOR	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Offside Front Strut top bearing noisy
MAJOR	Offside Parking brake inoperative on one side (1.4.1 (a))
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
MAJOR	Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #23	2021-07-13 18:29
MOT test number	506232970237
Result	✓ Passed

**MOT #22**

2021-06-18 09:52

MOT test number

597478486228

Result**✗ Failed**

- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Nearside Front Headlamp aim not tested (4.1.2 (b))
- MAJOR** Offside Front Headlamp light intensity severely reduced (4.1.4 (a))

MOT #21

2020-06-23 14:05

MOT test number

580805919944

Result**✓ Passed****MOT #20**

2020-06-12 10:53

MOT test number

890885698601

Result**✗ Failed**

- MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Subframe (5.3.6 (a) (i))
- MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Offside Headlamp aim too low (4.1.2 (a))
- MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Headlamp aim not tested (4.1.2 (b))



MOT #19	2019-05-18 14:41
MOT test number	228980735992
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #18	2019-05-14 11:00
MOT test number	143317043471
Result	✗ Failed
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
MAJOR	Offside Rear Coil spring worn so that its cross sectional area is reduced and seriously weakened (5.3.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #17	2018-05-14 11:50
MOT test number	500039672141
Result	✓ Passed
Advice	Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #16	2018-05-14 11:50
MOT test number	655112600246
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim beam image obviously incorrect Bulb fitted incorrectly (1.8.A.1b)
Pass with rectification	Battery insecure (1.9.1)
Advice	Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
Pass with rectification	Offside Headlamp aim too low (1.8)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #15**

2018-04-12 09:17

MOT test number

327029333019

Result**✗ Failed**

- Fail** Rear Parking brake lever has no reserve travel (3.1.6b)
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Front Windscreen wiper does not clear the windscreen effectively x2 (8.2.2)
- Fail** Offside Rear rear brake recording little or no effort hand brake (3.7.B.5a)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened x2 (3.5.1i)

MOT #14

2017-04-13 11:23

MOT test number

247697911194

Result**✓ Passed**

- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear Tyre worn close to the legal limit x2 (4.1.E.1)

**MOT #13**

2017-04-13 09:11

MOT test number

712091534460

Result**✗ Failed****Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Front Headlamp aim too high (1.8)**Advice** Rear Tyre worn close to the legal limit x2 (4.1.E.1)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Headlamp aim too high (1.8)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #12**

2016-04-22 13:10

MOT test number

115890015000

Result**✓ Passed****Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #11**

2016-04-22 10:18

MOT test number

276208810022

Result

✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)

MOT #10

2015-03-30 15:29

MOT test number

125999185061

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #9

2014-04-26 11:18

MOT test number

245886914159

Result

✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components
- Notice** Items removed from driver's view prior to test

**MOT #8** 2014-04-26 11:18**MOT test number** 689036714161**Result** ✗ Failed**Pass with rectification** Offside Rear Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Notice** Items removed from driver's view prior to test**MOT #7** 2013-04-11 16:03**MOT test number** 285471503438**Result** ✓ Passed**Notice** Nail in nearside rear tyre**Notice** Engine light on**MOT #6** 2013-04-10 10:30**MOT test number** 145990703132**Result** ✗ Failed**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Notice** Nail in nearside rear tyre**Fail** Nearside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Notice** Engine light on**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)

**MOT #5** 2012-04-27 14:55**MOT test number** 336708012176**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2011-03-04 14:10**MOT test number** 329983861098**Result** ✓ Passed**MOT #3** 2010-03-17 19:11**MOT test number** 384726370099**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2009-03-31 14:51**MOT test number** 671590399016**Result** ✓ Passed**MOT #1** 2008-03-28 17:15**MOT test number** 200558488002**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	YH05NTM
Plate since	2019-03-29
Current registration	YH05NTM
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2005-03-31
Last registration	2022-07-07
Complete history	See info



Registration #1	2005-03-31	16 mi
Registration #2	2008-03-28	31.129 mi
Registration #3	2009-03-31	38.630 mi
Registration #4	2010-03-17	46.822 mi
Registration #5	2011-03-04	53.922 mi
Registration #6	2012-04-27	60.643 mi
Registration #7	2013-04-10	67.595 mi
Registration #8	2013-04-11	67.596 mi
Registration #9	2014-04-26	75.259 mi
Registration #10	2015-03-30	82.156 mi
Registration #11	2016-04-22	88.349 mi
Registration #12	2016-04-22	88.350 mi
Registration #13	2017-04-13	92.043 mi
Registration #14	2018-04-26	95.277 mi
Registration #15	2019-04-26	95.277 mi
Registration #16	2020-04-26	95.277 mi
Registration #17	2021-04-26	95.277 mi
Registration #18	2022-04-26	95.277 mi
Registration #19	2023-04-26	95.277 mi
Registration #20	2024-04-26	95.277 mi
Registration #21	2025-04-26	95.277 mi
Registration #22	2026-04-26	95.277 mi
Registration #23	2027-04-26	95.277 mi
Registration #24	2028-04-26	95.277 mi
Registration #25	2029-04-26	95.277 mi
Registration #26	2030-04-26	95.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1960 mm
Height	1589 mm
Length	3792 mm
Wheel base	2482 mm
Kerb weight	1185 kg
Max. allowed weight	1675 kg

Additional information

Fuel tank capacity	49 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	D036263
---------------	---------