





report date: 2024-03-28

General information

Make	MINI
Model	COOPER AUTO COOPER S CLUBMAN
Colour	Red
Year of manufacture	2010
Top speed	138 mph
0 - 60 mph	7.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	190 BHP
Max. torque	240 Nm at 5.000 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2023-04-07

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1


Date	2021-09-12
Pictures	8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



Pass with rectification

LX10XRU report date: 2024-03-28

MOT history

MOT expiry date	2025-05-03
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	7
Total items failed	2

MOT #13	024-04-25 08:58
MOT test number	717558570447
Result	✓ Passed
Next expiry date	2025-05-03
Advice Exhaust has a minor leak of exhaust gases +front pipe flexy poor condition (6.1.2 (a))

MOT #12	2023-05-04 14:52
MOT test number	473867237803
Result	✓ Passed
MOT #11	2023-05-04 14:52
MOT test number	343632614028
Result	▼ Failed
Pass with rectification	Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #10	2022-07-07 14:43
MOT test number	853069362705
Result	✓ Passed

Offside Front Position lamp not working (4.2.1 (a) (ii))

CarCheck.co.uk page 3/12



LX10XRU

report date: 2024-03-28

MOT #9 2021-03-17 14:16

MOT test number 715264116993

Result
✓ Passed

MOT #8 2020-04-17 14:17

MOT test number 470827834894

Result Passed

Advice Wiper blade rubbers split

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7 2019-04-29 14:29

MOT test number 352419126797

Result \rightarrow Passed

MOT #6 2018-04-26 16:14

MOT test number 154198915809

Result ✓ Passed

MOT #5 2017-04-28 14:48

MOT test number 953216991685

Result \(\sqrt{Passed} \)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2016-04-21 16:28

MOT test number 211250650794

Result \(\sqrt{Passed} \)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/12



MOT #3 2015-04-22 10:05 **MOT test number** 388122615163 ✓ Passed Result MOT #2 2014-04-23 14:35 245633514162 **MOT test number** Result ✓ Passed MOT #1 2013-04-26 12:56 **MOT test number** 677896913118 Result ✓ Passed **Notice** Offside front tyre getting low **Notice** Offside rear jacking mount rubber missing

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	3 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-


CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history	
For how long did the current and previous owner(s) have this MINI? How many owners dicheck it in the premium report and see all owner registrations. Download the full report I	

HARMAN CO. C.	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
See in this check if this mini had different number plates.	
Number of plates	,
Correct registration	UK
Plate since	
Current registration	UK NIK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-04-28
Last registration	2024-04-25
Complete history	See info



Registration #1	2010-04-28	27 mi
Registration #2	2013-04-26	14.328 mi
Registration #3	2014-04-23	18.761 mi
Registration #4	2015-04-22	24.380 mi
Registration #5	2016-04-21	29.727 mi
Registration #6	2017-04-28	33.894 mi
Registration #7	2018-04-26	37.990 mi
Registration #8	2019-04-29	41.883 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		9.77 66
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1913 mm
Height	1432 mm
Length	3961 mm
Wheel base	2547 mm
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12

B4251731