





### General information

| Make                | VOLVO              |
|---------------------|--------------------|
| Model               | V60 D4 INSCRIPTION |
| Colour              | Blue               |
| Year of manufacture | 2016               |
| Top speed           | 140 mph            |
| 0 - 60 mph          | 7.9 seconds        |
| Gearbox             | 8 speed automatic  |

### Engine & fuel consumption

| Power                   | 190 BHP             |
|-------------------------|---------------------|
| Max. torque             | 400 Nm at 2.500 rpm |
| Engine capacity         | 1.969 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 53.3 mpg            |
| Consumption extra urban | 72.4 mpg            |
| Consumption combined    | 64.2 mpg            |
| CO2 emission            | 116 g/km            |
| CO2 label               | С                   |





BD66UGL report date: 2024-03-28

### Internet history

Entry 2

Date

Pictures

Listing price

2021-07-29 7

View report



#### source: yesauto.com

Entry 1

Date

Pictures

Listing price

2021-07-27 8

View report



source: autotrader.co.uk







## MOT history

| MOT expiry date    | 2024-08-25 |
|--------------------|------------|
| MOT pass rate      | 83 %       |
| MOT passed         | 5          |
| Failed MOT tests   | 1          |
| Total advice items | 5          |
| Total items failed | 2          |

| MOT #6           | 2023-08-25 12:52 |
|------------------|------------------|
| MOT test number  | 119838201700     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-08-25       |

| МОТ #5   | 2023-08-25 08:21 |
|--|------------------|
| MOT test number  | 529244386283     |
| Result   | 🗙 Failed         |
| <b>Fail</b> Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))  |                  |
| <b>Minor</b> Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |                  |
| <b>Fail</b> Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))  |                  |

| MOT #4          | 2022-08-23 10:07 |
|-----------------|------------------|
| MOT test number | 805757733256     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #3          | 2021-08-26 11:50 |
| MOT test number | 614188540410     |

Result

🗸 Passed



| MOT #2   | 2020-11-13 12:13 |
|--|------------------|
| MOT test number  | 288841780691     |
| Result   | ✓ Passed         |
| Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))        |                  |
| Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |                  |
| Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))                          |                  |
| Advice Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))       |                  |
|  |                  |

| MOT #1          | 2019-12-06 12:55 |
|-----------------|------------------|
| MOT test number | 469423116659     |
| Result          | ✓ Passed         |



Tax & MOT check

| ✓<br>Taxed<br>Tax due:<br>1 August 2024 | ✓<br>MOT<br>Expires:<br>25 August 2024 |
|---|--|
| Tax status                              | Valid until 1 August                   |
| Days left                               | 94                                     |
| MOT expiry date                         | 25 August 2024                         |
| Full MOT history                        | See MOT history                        |
| Tax calculation                         |  |
| Vehicle class                           | 49                                     |

| Band                                    | С              |
|---|----------------|
| Single payment (12 months)              | £ 35,00,-      |
| Single six month payment                | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,-      |





### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |          |
|----------|----------|
| Date     | FEIDO    |
| Category | 4. ARMPE |
| Туре     |          |
| Damage 2 | AMPL     |
|          | F Stores |
| Date     | 1.E      |
| Category | ante     |
| Туре     |          |

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4.00.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ana                      |             |
|--|-------------|
| ***********  |             |
| *******  |             |
| ******   |             |
| ***********  |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this VOLVO had different number plates. |             |
| Number of plates   | ,           |
| Current registration   |             |
| Plate since  |             |
| Current registration   |             |
| Plate since  |             |
|  | More info > |





#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |


More info  $\rightarrow$ 



BD66UGL report date: 2024-03-28

# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 9          |
| First mileage registration | 2016-12-09 |
| Last registration          | 2023-08-25 |
| Complete history           | See info   |



| Registration #1 | 2016-12-09 | 29 mi      |
|-----------------|------------|------------|
| Registration #2 | 2019-12-06 | 40.101 mi  |
| Registration #3 | 2020-11-13 | 44.794 mi  |
| Registration #4 |            | 11.777 esi |
| Registration #5 |            | 11.777 mi  |
| Registration #6 |            | 11.777 esi |
| Registration #7 |            | 11.777 mi  |
| Registration #8 |            | 11.777 esi |
| Registration #9 |            | 11.117 esi |

More info >





## Car features

| S0225  | Air conditioning |
|--------|------------------|
| \$0295 |                  |
| 50482  |                  |
| \$0501 |                  |
| \$0566 |                  |
| \$0567 |                  |
| S0569  |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 94%             |
| Children       | 82%             |
| Pedestrian     | 64%             |
| Safety systems | 100%            |
| Overall rating | 86%             |
| Video          | see crash video |



| Dimensions & weight               |                  |
|-----------------------------------|------------------|
| Width                             | 2019 mm          |
| Height                            | 1443 mm          |
| Length                            | 4963 mm          |
| Wheel base                        | 2941 mm          |
| Kerb weight                       | 1680 kg          |
| Max. allowed weight               | 2270 kg          |
| Additional information            |                  |
| Fuel tank capacity                | 55 l             |
| Fuel delivery                     | Direct Injection |
| Number of doors                   | 4                |
| Number of seats<br>CarCheck.co.uk | 5 page 11/11     |