



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC SL27 DCI 115 SWB P/V
Colour	Silver
Year of manufacture	2007
Top speed	99 mph
0 - 60 mph	15.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	40.4 mpg
Consumption combined	35.8 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2021-03-25
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	34
Total items failed	7

MOT #16 2020-03-13 16:28

MOT test number 690870807896

Result ✓ Passed

Next expiry date 2021-03-25

- Advice** Nearside Front tyre worn at edges
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Central stop light inop

MOT #15 2020-03-07 11:39

MOT test number 649353635808

Result ✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front tyre worn at edges
- MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Central stop light inop
- MAJOR** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #14** 2019-03-22 15:43**MOT test number** 280200369130**Result** ✓ Passed**MOT #13** 2019-03-21 13:09**MOT test number** 599850284956**Result** ✗ Failed**Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**DANGEROUS** Nearside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))**MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #12** 2018-03-26 08:55**MOT test number** 973359845151**Result** ✓ Passed**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)

**MOT #11** 2017-02-22 15:10**MOT test number** 735609202813**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2017-02-22 10:42**MOT test number** 768194108895**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Seat belt locking mechanism does not secure or release (5.2.5a)**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #9** 2016-03-21 10:43**MOT test number** 192999994799**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2015-06-10 12:45**MOT test number** 526921765135**Result** ✓ Passed

**MOT #7** 2014-04-14 14:09**MOT test number** 467234504119**Result** ✓ Passed**MOT #6** 2014-04-11 16:15**MOT test number** 968431304167**Result** ✗ Failed**Fail** Front brake application uneven (3.7.B.2)**Fail** Nearside Front front brake binding (3.7.B.1)**MOT #5** 2013-03-05 12:42**MOT test number** 608034663019**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Upper Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Upper Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #4** 2012-03-06 08:03**MOT test number** 838776362055**Result** ✓ Passed**MOT #3** 2012-02-25 10:00**MOT test number** 187466152460**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)



MOT #2	2011-02-28 09:59
MOT test number	259589151038
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2010-03-01 15:42
MOT test number	974360460058
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
18 December 2020

✕
MOT

Expired:
25 March 2021

Tax status

Expired at 18 December 2020

Days left

1229 days too late

MOT expiry date

25 March 2021

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-03-02
Last registration	2020-03-13
Complete history	See info



Registration #1	2007-03-02	21 mi
Registration #2	2010-03-01	45.968 mi
Registration #3	2011-02-28	68.926 mi
Registration #4	2012-02-25	79.353 mi
Registration #5	2012-03-06	79.355 mi
Registration #6	2013-03-05	92.665 mi
Registration #7	2014-04-11	105.916 mi
Registration #8	2014-04-14	105.918 mi
Registration #9	2015-06-10	116.489 mi
Registration #10	2016-06-20	121.277 mi
Registration #11	2017-06-20	121.277 mi
Registration #12	2018-06-20	121.277 mi
Registration #13	2019-06-20	121.277 mi
Registration #14	2020-06-20	121.277 mi
Registration #15	2021-06-20	121.277 mi
Registration #16	2022-06-20	121.277 mi
Registration #17	2023-06-20	121.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2232 mm
Height	1944 mm
Length	4782 mm

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C100792