





report date: 2024-03-29

General information

Make	FIAT
Model	500L MULTIJET POP STAR
Colour	White
Year of manufacture	2014
Top speed	112 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

F	n	t	r۱	,	2
_				,	_

, -	
Date	2021-09-24
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-09-23
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2025-03-24
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	7
Total items failed	12

MOT #10	2024-03-25 13:04
MOT test number	289644027125
Result	✓ Passed
Next expiry date	2025-03-24
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #9	2023-03-22 12:16
MOT test number	566552759736
Result	✓ Passed

MOT #8	2023-03-21 09:53
--------	------------------

MOT test number 514774667586

Result X Failed

Fail Nearside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Result

Minor

Rear Windscreen wiper blade defective (3.4 (b) (i))

Advice

Child Seat fitted not allowing full inspection of adult belt

MOT test number

Result

Advice Child Seat fitted not allowing full inspection of adult belt

Minor Rear Windscreen wiper blade defective (3.4 (b) (i))

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

MOT #5 2021-03-22 10:15 279722805129 **MOT** test number Result Passed **MOT #4** 2021-03-09 10:27 **MOT** test number 765206507367 Result × Failed Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii)) Fail Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Nearside Rear Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #3 2020-02-27 10:05
MOT test number 524214042619

Result ✓ Passed

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Outer Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MOT #2 2019-02-22 09:53

MOT test number 259200257109

Result ✓ Passed

MOT #1 2018-01-25 14:39

MOT test number 243438636474

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	24 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



WV640BA report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>I</u>	

Plate changes	More info >
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-09-01
Last registration	2024-03-25
Complete history	See info



Registration #1	2014-09-01	20 mi
Registration #2	2018-01-25	60.428 mi
Registration #3	2019-02-22	72.832 mi
Registration #4	2020-02-27	83.783 mi
Registration #5	2021-03-09	88.362 mi
Registration #6	2021-03-22	88.366 mi
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		11.777 mi
Registration #12		0.00 44
Registration #13		10.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2018 mm
Height	1667 mm
Length	4147 mm
Wheel base	2612 mm
Kerb weight	1365 kg
Max. allowed weight	1925 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles2Engine number6946424