



General information

Make	FORD
Model	MONDEO TITANIUM X TDCI 140
Colour	Blue
Year of manufacture	2009
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	154 g/km
CO2 label	G





MOT history

MOT expiry date	2023-05-13
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	43
Total items failed	26

**MOT #18**

2023-05-16 13:34

MOT test number

640784711338

Result**✗ Failed**

- Fail** Front Service brake excessively fluctuating (1.2.1 (e))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
- Minor** Offside Front Position lamp incorrect colour (4.2.3 (a) (i))
- Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Exhaust diesel particulate filter shows evidence of tampering. (8.2.2.1 (c))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Fail** Nearside Front Shock absorbers has negligible damping effect (5.3.2 (d))
- Fail** Front Headlamp light source and lamp not compatible (4.1.4 (c))
- Minor** Nearside Front Position lamp incorrect colour (4.2.3 (a) (i))
- Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #17**

2022-05-14 08:26

MOT test number

972109323446

Result

✓ Passed

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear exhaust heat shield slightly insecure, but not likely to become detached
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))

MOT #16

2022-05-09 12:59

MOT test number

513111756705

Result

✗ Failed

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Rear Direction indicator not working (4.4.1 (a) (ii))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Rear exhaust heat shield slightly insecure, but not likely to become detached
- Fail** Offside Seat belt anchorage prescribed area strength or continuity significantly reduced Outer sill (7.1.1 (a) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15**

2021-05-04 13:05

MOT test number

624455365082

Result

✓ Passed

Advice Offside Seat belt anchorage prescribed area is corroded but not considered excessive repair covered in underseal (7.1.1 (a) (i))

MOT #14

2021-05-04 13:05

MOT test number

334036692567

Result

✗ Failed

Advice Offside Seat belt anchorage prescribed area is corroded but not considered excessive repair covered in underseal (7.1.1 (a) (i))

Pass with rectification Central Front Position lamp not working (4.2.1 (a) (ii))

MOT #13

2021-03-12 10:46

MOT test number

916798850946

Result

✗ Failed

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Offside Front Outer Seat belt anchorage prescribed area strength or continuity significantly reduced Sill (7.1.1 (a) (i))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Exhaust mounting defective (6.1.2 (a))

MOT #12

2020-02-18 16:57

MOT test number

716777056071

Result

✓ Passed

Advice Items removed from driver's view prior to test

**MOT #11** 2020-02-18 16:57**MOT test number** 296291950221**Result** ✗ Failed**Advice** Items removed from driver's view prior to test**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #10** 2019-02-20 09:38**MOT test number** 355771138495**Result** ✓ Passed**Advice** Front tyres wearing inside edges**MOT #9** 2019-02-14 16:44**MOT test number** 637443524628**Result** ✗ Failed**Fail** Offside Rear Suspension arm pin or bush excessively worn trail arm bush (5.3.4 (a) (i))**Advice** Front tyres wearing inside edges**Fail** Offside Front Suspension component mounting prescribed area is corroded to the extent that control of the vehicle is likely to be adversely affected outer sill (5.3.6 (a) (ii))**Fail** Nearside Rear Suspension arm pin or bush excessively worn trail arm bush (5.3.4 (a) (i))**MOT #8** 2018-01-23 14:32**MOT test number** 925160775273**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Tyre pressure monitoring system warning lamp does not illuminate (4.1.D.4)

**MOT #7** 2018-01-04 14:47**MOT test number** 286387849337**Result** ✗ Failed

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Fail** Rear brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail** Rear fog lamp not working (1.3.2b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)

MOT #6 2017-05-19 14:01**MOT test number** 276737873194**Result** ✓ Passed

- Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Brake cable has wires broken but is not significantly weakened (3.5.1b)
- Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Brake cable has wires broken but is not significantly weakened (3.5.1b)
- Advice** Offside Front Outer Body has slight corrosion sill corroded (6.1.B.2)

**MOT #5** 2016-05-17 13:06**MOT test number** 950704715989**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2015-05-25 16:53**MOT test number** 607325345135**Result** ✓ Passed**MOT #3** 2014-11-19 11:10**MOT test number** 257363024312**Result** ✓ Passed**MOT #2** 2013-11-20 10:18**MOT test number** 989844523329**Result** ✓ Passed**MOT #1** 2012-11-23 13:51**MOT test number** 379408722334**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
31 July 2023

X

MOT

Expired:
13 May 2023

Tax status	Expired at 31 July 2023
Days left	274 days too late
MOT expiry date	13 May 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-11-23
Last registration	2023-05-16
Complete history	See info



Registration #1	2009-11-23	20 mi
Registration #2	2012-11-23	21.409 mi
Registration #3	2013-11-20	27.457 mi
Registration #4	2014-11-19	33.745 mi
Registration #5	2015-05-25	37.363 mi
Registration #6	2016-05-17	46.781 mi
Registration #7	2017-05-19	57.326 mi
Registration #8	2018-01-04	62.254 mi
Registration #9	2018-01-23	62.265 mi
Registration #10	2019-02-14	72.786 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2019-05-20	75.277 mi
Registration #13	2019-05-20	75.277 mi
Registration #14	2019-05-20	75.277 mi
Registration #15	2019-05-20	75.277 mi
Registration #16	2019-05-20	75.277 mi
Registration #17	2019-05-20	75.277 mi
Registration #18	2019-05-20	75.277 mi
Registration #19	2019-05-20	75.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

9C62374