



report date: 2024-03-29

General information

Make	NISSAN
Model	PRIMERA S
Colour	Blue
Year of manufacture	-
Top speed	121 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	163 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	38.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-18
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #18	2020-11-23 10:38
MOT test number	373554621604
Result	✓ Passed
Next expiry date	2021-12-07
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))	
Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))	

MOT #17	2019-12-02 11:31
MOT test number	539125927865
Result	✓ Passed
Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Service brake binding but not excessively (1.2.1 (f))	
Advice Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	

MOT #16	2019-12-02 11:31
MOT test number	228615543659
Result	✗ Failed
Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Pass with rectification Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))	
Advice Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Advice Offside Front Service brake binding but not excessively (1.2.1 (f))	

**MOT #15** 2018-11-24 14:39**MOT test number** 830636008279**Result** ✓ Passed

Advice Power steering component has slight seepage from a component steering rack slight leak (2.1.5 (a))

Minor Offside Front Windscreen wiper blade defective wiper blade split on end (3.4 (b) (i))

MOT #14 2018-11-23 14:07**MOT test number** 497275488239**Result** ✗ Failed

Fail Offside Front Headlamp aim too low (4.1.2 (a))

Advice Power steering component has slight seepage from a component steering rack slight leak (2.1.5 (a))

Minor Offside Front Windscreen wiper blade defective wiper blade split on end (3.4 (b) (i))

MOT #13 2017-11-20 17:20**MOT test number** 919255775587**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit tyre on 1.6-2mm 215/50/17 (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit tyre on 2-3mm (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit tyre on 2-3mm (4.1.E.1)

**MOT #12** 2017-11-18 11:01**MOT test number** 296763092356**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit tyre on 2-3mm (4.1.E.1)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit tyre on 1.6-2mm 215/50/17 (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit tyre on 2-3mm (4.1.E.1)**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front brake discs lipped (3.5.1i)**MOT #11** 2016-11-15 17:40**MOT test number** 197070878894**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Power steering component(s) has slight seepage from a component rack and pinion housing (2.3.3b)**MOT #10** 2015-12-02 14:47**MOT test number** 151764434724**Result** ✓ Passed**Advice** Power steering component(s) has slight seepage from a component @ rack boots o/s and n/s (2.3.3b)

**MOT #9** 2014-11-17 12:00**MOT test number** 726671924396**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Notice** Items removed from driver's view prior to test**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Power steering component(s) has slight seepage from a component (2.3.3b)**MOT #8** 2013-12-04 09:24**MOT test number** 417398533360**Result** ✓ Passed**MOT #7** 2012-11-15 14:58**MOT test number** 926320922359**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2011-11-16 11:25**MOT test number** 847780921367**Result** ✓ Passed**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Nearside Rear Seat belt stitching slightly frayed (5.2.2b)**MOT #5** 2010-11-23 10:16**MOT test number** 362767820337**Result** ✓ Passed**Advice** Nearside Rear Seat belt stitching slightly frayed (5.2.2b)

**MOT #4** 2010-11-23 10:16**MOT test number** 170657720337**Result** ✗ Failed

Pass with rectification Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

Advice Nearside Rear Seat belt stitching slightly frayed (5.2.2b)

MOT #3 2009-12-08 15:42**MOT test number** 434832949426**Result** ✓ Passed

Advice Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Seat belt stitching slightly frayed (5.2.2b)

MOT #2 2008-08-14 09:18**MOT test number** 763087128280**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2007-08-23 16:52**MOT test number** 124265537270**Result** ✓ Passed

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2004-08-12
Last registration	2020-11-23
Complete history	See info



Registration #1	2004-08-12	20 mi
Registration #2	2007-08-23	30.456 mi
Registration #3	2008-08-14	39.893 mi
Registration #4	2009-12-08	44.899 mi
Registration #5	2010-11-23	47.476 mi
Registration #6	2011-11-16	50.468 mi
Registration #7	2012-11-15	52.905 mi
Registration #8	2013-12-04	55.926 mi
Registration #9	2014-11-17	58.551 mi
Registration #10	2015-12-02	60.541 mi
Registration #11	2016-11-16	62.531 mi
Registration #12	2017-11-15	64.521 mi
Registration #13	2018-11-14	66.511 mi
Registration #14	2019-11-13	68.501 mi
Registration #15	2020-11-12	70.491 mi
Registration #16	2021-11-11	72.481 mi
Registration #17	2022-11-10	74.471 mi
Registration #18	2023-11-09	76.461 mi
Registration #19	2024-11-08	78.451 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1488 mm
Length	4567 mm
Wheel base	2680 mm
Kerb weight	1361 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	330821