



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 R-DESIGN SE PREMIUM
Colour	Grey
Year of manufacture	2009
Top speed	137 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	205 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	183 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-08-01
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-30
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	15
Total items failed	11

MOT #17	2023-08-25 08:46
MOT test number	124909349474
Result	✓ Passed
Next expiry date	2024-08-30
Advice	Front Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

MOT #16	2023-08-24 13:44
MOT test number	663950652428
Result	✗ Failed
Fail	Nearside Windscreen washer not working (3.5 (a))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Front Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

MOT #15	2022-08-31 10:13
MOT test number	329684897806
Result	✓ Passed
Advice	Rear Brake disc worn, but not excessively both n/s and o/s lipped (1.1.14 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 245/40/18 (5.2.3 (e))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 245/40/18 (5.2.3 (e))



MOT #14	2021-08-11 14:08
----------------	------------------

MOT test number	866498456420
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
---------------	---

MOT #13	2020-10-23 08:18
----------------	------------------

MOT test number	989498356270
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
---------------	--

MOT #12	2019-10-26 11:29
----------------	------------------

MOT test number	209485930462
------------------------	--------------

Result	✓ Passed
---------------	----------

**MOT #11**

2019-10-23 15:22

MOT test number

724173008125

Result**✗ Failed**

- Fail** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10

2018-10-04 08:40

MOT test number

831535968422

Result**✓ Passed****MOT #9**

2018-10-03 14:32

MOT test number

390889439489

Result**✗ Failed**

- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #8

2017-10-04 13:35

MOT test number

911230211329

Result**✓ Passed**

**MOT #7** 2016-09-16 13:18**MOT test number** 165294231663**Result** ✓ Passed**MOT #6** 2015-09-18 14:48**MOT test number** 765528164457**Result** ✓ Passed**MOT #5** 2015-09-18 08:51**MOT test number** 785684588630**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #4** 2014-09-26 16:36**MOT test number** 375829764423**Result** ✓ Passed**MOT #3** 2013-09-27 09:58**MOT test number** 428980973200**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-09-27 09:58**MOT test number** 977140773249**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low and too far to the left. (1.8)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2012-09-11 12:30
MOT test number	115025052210
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
30 August 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	30 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	AK59VRV
Plate since	2019-03-29
Current registration	AK59VRV
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-21
Last registration	2023-08-25
Complete history	See info



Registration #1	2009-09-21	26 mi
Registration #2	2012-09-11	42.840 mi
Registration #3	2013-09-27	50.492 mi
Registration #4	2014-09-26	57.398 mi
Registration #5	2015-09-18	65.236 mi
Registration #6	2015-09-18	65.236 mi
Registration #7	2016-09-16	73.125 mi
Registration #8	2017-10-04	81.254 mi
Registration #9	2018-10-03	89.506 mi
Registration #10	2019-09-21	95.277 mi
Registration #11	2019-09-21	95.277 mi
Registration #12	2019-09-21	95.277 mi
Registration #13	2019-09-21	95.277 mi
Registration #14	2019-09-21	95.277 mi
Registration #15	2019-09-21	95.277 mi
Registration #16	2019-09-21	95.277 mi
Registration #17	2019-09-21	95.277 mi
Registration #18	2019-09-21	95.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1781 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	737752