





General information

| Make | LAND ROVER |
|---------------------|------------------------------|
| Model | DEFENDER TD XS STATION WAGON |
| Colour | Grey |
| Year of manufacture | 2010 |
| Top speed | 82 mph |
| 0 - 60 mph | 15.8 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 121 BHP |
|-------------------------|---------------------|
| Max. torque | 360 Nm at 2.000 rpm |
| Engine capacity | 2.402 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 20.8 mpg |
| Consumption extra urban | 29.1 mpg |
| Consumption combined | 25.5 mpg |





Internet history

| Entry 2 | | | |
|--|-------------|---|--|
| Date | 2021-07-15 | | |
| Pictures | 6 | | |
| Listing price | View report | | |
| interest int | | <image/> <image/> <text><text><text><text><text></text></text></text></text></text> | We are HIGHLY RATED Ly our autometri reviews on AutoTrader 2019 Mead our reviews or recommend us taday |

| Entry 1 | | |
|---------------|-------------|--|
| Date | 2021-07-10 | |
| Pictures | 4 | |
| Listing price | View report | |
| | | |
| | | |



source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-08-10 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 12 |
| Failed MOT tests | 3 |
| Total advice items | 8 |
| Total items failed | 3 |

| MOT #15 | 2023-08-10 12:03 | |
|-----------|---|--|
| MOT test | number 966302200613 | |
| Result | ✓ Passed | |
| Next expi | ry date 2024-08-10 | |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing age cracked on sidewall (5.2.3 (d) (ii)) | |
| Advice | Offside Front swivle hub seal seapage | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing age cracked on sidewall (5.2.3 (d) (ii)) | |
| Advice | Nearside Front swivle hub seal seapage | |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing age cracked on sidewall (5.2.3 (d) (ii)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing age cracked on sidewall (5.2.3 (d) (ii)) | |

| MOT #14 | 2022-08-02 11:03 |
|---|-------------------------------|
| MOT test number | 976549063412 |
| Result | ✓ Passed |
| Advice Front passenger door catch deteriorated but the door can still be rehandle loose (6.2.3 (c) (i)) | eadily opened and closed door |

| MOT #13 | 2021-08-11 16:35 |
|-----------------|------------------|
| MOT test number | 650796188510 |
| Result | ✓ Passed |



GK10WLN report date: 2024-03-28

| MOT #12 | 2021-02-26 18:11 |
|---|--|
| MOT test number | 942392438572 |
| Result | ✓ Passed |
| | |
| MOT #11 | 2021-02-26 18:11 |
| MOT test number | 795322608910 |
| Result | × Failed |
| Pass with rectification PADS (1.1.14 (a) (ii)) | Brake disc in such a condition that it is seriously weakened BOTH REAR DISCS |
| MOT #10 | 2020-02-06 14:29 |
| MOT test number | 881998139781 |
| Result | ✓ Passed |
| | |
| МОТ #9 | 2019-01-29 14:14 |
| MOT test number | 816517236032 |
| Result | ✓ Passed |
| | |
| MOT #8 | 2018-01-29 10:58 |
| MOT test number | 172467894965 |
| Result | ✓ Passed |
| MOT #7 | 2017-02-02 12:29 |
| MOT #7 MOT test number | 422203453757 |
| Result | ✓ Passed |
| Result | V I doseu |
| MOT #6 | 2016-02-09 18:21 |
| MOT test number | 874252141543 |
| Result | ✓ Passed |
| | |






| MOT #5 | 2016-02-09 10:13 |
|--|-------------------|
| MOT test number | 925915334922 |
| Result | 🗙 Failed |
| Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c) | |
| MOT #4 | 2015-02-02 17:36 |
| MOT test number | 195363235410 |
| Result | 🗸 Passed |
| | |
| MOT #3 | 2015-02-02 12:57 |
| MOT test number | 348673635045 |
| Result | 🗙 Failed |
| Fail Nearside Rear Anti-roll bar linkage ball joint dust cover excessively damaged so to prevents the ingress of dirt (2.4.G.2) | that it no longer |
| MOT #2 | 2014-02-04 13:44 |
| MOT test number | 716505734071 |
| Result | 🗸 Passed |
| | |
| MOT #1 | 2013-03-07 09:35 |
| MOT test number | 968976363014 |
| Result | ✓ Passed |
| Notice Custmer says ABS light comes on but this was not seen at time of test. | |



GK10WLN report date: 2024-03-28

Tax & MOT check







Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Date | |
| | MP1E |
| Category | ter . |
| Туре | |

Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| NUMBER OF CONTRACTOR OF CONTRACT | | |
|--|-----------|---|
| ********** | | |
| ******** | | |
| ******* | | |
| ********* | | |
| ******** | | |
| | More info | > |
| | | |
| Plate changes | | |
| See in this check if this LAND ROVER had different number plates. | | |





Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 18 |
| First mileage registration | 2010-03-16 |
| Last registration | 2023-08-10 |
| Complete history | <u>See info</u> |



| Registration #1 | 2010-03-16 | 12 mi |
|------------------|------------|------------|
| Registration #2 | 2013-03-07 | 13.682 mi |
| Registration #3 | 2014-02-04 | 16.251 mi |
| Registration #4 | 2015-02-02 | 18.019 mi |
| Registration #5 | 2015-02-02 | 18.019 mi |
| Registration #6 | 2016-02-09 | 18.132 mi |
| Registration #7 | 2016-02-09 | 18.132 mi |
| Registration #8 | 2017-02-02 | 20.621 mi |
| Registration #9 | 2018-01-29 | 23.227 mi |
| Registration #10 | | 11.777 est |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.777 mi |
| Registration #14 | | 11.777 esi |
| Registration #15 | | 11.777 mi |
| Registration #16 | | 11.777 est |
| Registration #17 | | 11.777 est |
| Registration #18 | | 11.117 mi |

More info \rightarrow





Dimensions & weight

| Width | 1790 mm |
|------------------------|---------|
| Height | 2181 mm |
| Length | 4625 mm |
| Kerb weight | 2111 kg |
| Max. allowed weight | 3050 kg |
| Additional information | |

| Fuel delivery | Direct Injection |
|-----------------|-------------------|
| Number of doors | 5 |
| Number of seats | 7 |
| Number of axles | 2 |
| Engine number | 100921212117244DT |