




report date: 2024-03-29

General information

Make	VOLVO
Model	V70 T SE
Colour	Black
Year of manufacture	2007
Top speed	137 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	20.2 mpg
Consumption extra urban	38.2 mpg
Consumption combined	27.7 mpg
CO2 emission	243 g/km
CO2 label	L





Internet history

Entry 2

Date	2021-10-19
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-18
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-04
MOT pass rate	100 %
MOT passed	14
Failed MOT tests	0
Total advice items	9
Total items failed	0

MOT #14	2023-10-28 09:39
MOT test number	244008256599
Result	✓ Passed
Next expiry date	2024-11-04

MOT #13	2022-11-05 16:03
MOT test number	700631863604
Result	✓ Passed
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Minor	Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #12	2021-09-17 05:51
MOT test number	359650182973
Result	✓ Passed

MOT #11	2020-09-24 06:16
MOT test number	565847250103
Result	✓ Passed

MOT #10	2019-10-09 13:35
MOT test number	690562216580
Result	✓ Passed

**MOT #9** 2018-10-16 10:36**MOT test number** 475309564526**Result** ✓ Passed**Advice** Exhaust mounting defective centre hanger bracket missing (6.1.2 (a))**MOT #8** 2017-10-06 16:15**MOT test number** 515534578669**Result** ✓ Passed**MOT #7** 2016-12-14 13:07**MOT test number** 677599208434**Result** ✓ Passed**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6** 2015-12-10 10:13**MOT test number** 482802033189**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-12-12 10:31**MOT test number** 417996144366**Result** ✓ Passed



MOT #4	2013-12-12 10:15
MOT test number	716826043360
Result	✓ Passed
MOT #3	2012-12-06 09:45
MOT test number	206331442317
Result	✓ Passed
MOT #2	2011-12-07 12:14
MOT test number	799401941369
Result	✓ Passed
MOT #1	2010-12-13 15:29
MOT test number	541887840391
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✓
MOT

Expires:
4 November 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	4 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-12-31
Last registration	2023-10-28
Complete history	See info



Registration #1	2007-12-31	14 mi
Registration #2	2010-12-13	15.719 mi
Registration #3	2011-12-07	19.586 mi
Registration #4	2012-12-06	23.040 mi
Registration #5	2013-12-12	26.189 mi
Registration #6	2014-12-12	29.922 mi
Registration #7	2015-12-10	31.880 mi
Registration #8	2016-12-14	34.725 mi
Registration #9	2017-10-06	35.349 mi
Registration #10	2018-05-22	36.277 mi
Registration #11	2019-05-22	36.277 mi
Registration #12	2020-05-22	36.277 mi
Registration #13	2021-05-22	36.277 mi
Registration #14	2022-05-22	36.277 mi
Registration #15	2023-05-22	36.277 mi
Registration #16	2024-05-22	36.277 mi
Registration #17	2025-05-22	36.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1747 kg
Max. allowed weight	2280 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	4199933