





report date: 2024-03-28

General information

Make	MINI
Model	MINI (R60) ONE D
Colour	White
Year of manufacture	2011
Top speed	106 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history


Entry 1

Date 2021-10-15

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-05-24
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	12
Total items failed	5

MOT #13	2023-05-11 10:35
MOT test number	307482358178
Result	✓ Passed
Next expiry date 2024-05-2	
Advice Offside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))	

MOT #12	2023-05-11 08:12
MOT test number	665095969263
Result	X Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords cracked on inner edge (5.2.3 (d) (i))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords cracked on inner edge (5.2.3 (d) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))

MOT #11		2022-05-25 16:36
MOT test	number	396665815667
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 225/45/18 (5.2.3 (e))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #10 2022-05-25 10:08 **MOT test number** 450653772216 Result × Failed **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii)) Advice Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Service brake efficiency below requirements (1.2.2 (a) (i)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 225/45/18 (5.2.3 (e))

MOT #9		2021-07-14 10:27
MOT test	number	861581311444
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #8	2020-07-15 09:31
MOT test number	267834383534
Result	✓ Passed
MOT #7	2019-04-08 12:28
MOT test number	598311752982
Result	✓ Passed
MOT #6	2018-05-19 15:10
MOT test number	704258327736
Result	✓ Passed
Advice Oil leak	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5		2017-05-30 07:59
MOT test number		911181099407
Result		✓ Passed
MOT #4		2016-05-21 08:39
MOT test number		558316313180
Result		✓ Passed
MOT #3		2015-06-04 13:05
MOT test number		298435755123
Result		x Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)	
Pass with rectification	Offside Headlamp aim too low (1.8)	

MOT #2	2015-06-04 13:05
MOT test number	667215155116
Result	✓ Passed
MOT #1	2014-11-04 11:49
MOT test number	969428404321
Result	✓ Passed

CarCheck.co.uk page 5/12



HV61ETU report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	24 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



HV61ETU report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

e union mestery	
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	UK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-12-17
Last registration	2023-05-11
Complete history	See info



Registration #1	2011-12-17	10 mi
Registration #2	2014-11-04	27.408 mi
Registration #3	2015-06-04	31.828 mi
Registration #4	2016-05-21	37.676 mi
Registration #5	2017-05-30	45.023 mi
Registration #6	2018-05-19	50.683 mi
Registration #7	2019-04-08	56.919 mi
Registration #8		11.777 es
Registration #9		11.177 es
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		11.177 es
Registration #13		11.777 46

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



HV61ETU report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	47
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12

Engine number

73317833