



report date: 2024-03-29

General information

| | |
|---------------------|-----------------------------------|
| Make | CITROEN |
| Model | C4 CACTUS PURETECH FLAIR S/S EAT6 |
| Colour | Grey |
| Year of manufacture | 2018 |
| Top speed | 117 mph |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 108 BHP |
| Max. torque | 205 Nm at 1.500 rpm |
| Engine capacity | 1.200 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 44.1 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 53.3 mpg |
| CO2 emission | 117 g/km |
| CO2 label | C |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-02-21 |
| Pictures | 1 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-04-02 |
| MOT pass rate | 57 % |
| MOT passed | 4 |
| Failed MOT tests | 3 |
| Total advice items | 12 |
| Total items failed | 11 |

| | |
|------------------|---|
| MOT #7 | 2024-04-03 15:07 |
| MOT test number | 189539366963 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-02 |
| Minor | Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) |
| Minor | Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| Minor | Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) |

| | |
|-------------------------|---|
| MOT #6 | 2024-04-03 15:07 |
| MOT test number | 544379434269 |
| Result | ✗ Failed |
| Minor | Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| Minor | Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) |
| Pass with rectification | Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)) |
| Pass with rectification | Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) |
| Minor | Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) |
| Pass with rectification | Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) |

**MOT #5** 2023-04-03 10:18**MOT test number** 884173652710**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing 205/50/17 3.5mm (5.2.3 (d) (ii))**MOT #4** 2023-04-03 08:42**MOT test number** 942210198880**Result** ✗ Failed**Advice** Engine oil on min**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing 205/50/17 3.5mm (5.2.3 (d) (ii))**MOT #3** 2022-03-30 14:47**MOT test number** 579964199968**Result** ✓ Passed**MOT #2** 2021-12-16 16:11**MOT test number** 710684411794**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



| | |
|-----------------|---|
| MOT #1 | 2021-12-16 09:10 |
| MOT test number | 406323695264 |
| Result | ✗ Failed |
| Fail | Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) |
| Fail | Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Fail | Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) |



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
2 April 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 336 |
| MOT expiry date | 2 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 0 |
| Current registration | KR68VCA |
| Plate since | 2019-09-29 |
| Current registration | KR68VCA |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 9 |
| First mileage registration | 2018-11-26 |
| Last registration | 2024-04-03 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2018-11-26 | 28 mi |
| Registration #2 | 2021-12-16 | 44.955 mi |
| Registration #3 | 2021-12-16 | 44.955 mi |
| Registration #4 | 2021-12-16 | 44.955 mi |
| Registration #5 | 2022-03-30 | 45.314 mi |
| Registration #6 | 2022-03-30 | 45.314 mi |
| Registration #7 | 2022-03-30 | 45.314 mi |
| Registration #8 | 2022-03-30 | 45.314 mi |
| Registration #9 | 2022-03-30 | 45.314 mi |

More info >



Safety ratings

| | | |
|----------------|---------------------------------|---|
| NCAP rating | ★★★★☆ | ▢ |
| Adult | 82% | |
| Children | 79% | |
| Pedestrian | 80% | |
| Safety systems | 56% | |
| Overall rating | 76% | |
| Video | see crash video | |

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1979 mm |
| Height | 1480 mm |
| Length | 4170 mm |
| Wheel base | 2595 mm |
| Kerb weight | 1090 kg |
| Max. allowed weight | 1620 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 50 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Engine number | XVAZ1190701 |