



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D SE
Colour	Grey
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-01-14
Pictures	14
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-01-14
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	14
Total items failed	3

## MOT #14 2024-01-15 17:09

MOT test number 103849647853

Result ✓ Passed

Next expiry date 2025-01-14

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

## MOT #13 2024-01-15 17:09

MOT test number 762591123714

Result ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

**MOT #12** 2023-01-09 10:47**MOT test number** 970113091494**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #11** 2022-01-14 16:31**MOT test number** 473172022402**Result** ✓ Passed**MOT #10** 2020-11-26 11:53**MOT test number** 488293063672**Result** ✓ Passed**Advice** Front Inner Tyre worn close to legal limit/worn on edge Both side (5.2.3 (e))**MOT #9** 2019-11-28 17:30**MOT test number** 882340274422**Result** ✓ Passed**MOT #8** 2018-11-17 10:13**MOT test number** 925859022006**Result** ✓ Passed

**MOT #7** 2017-12-08 09:51**MOT test number** 778398557283**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened bothsides (3.5.1i)**MOT #6** 2016-12-09 13:34**MOT test number** 201280978287**Result** ✓ Passed**MOT #5** 2015-12-08 12:14**MOT test number** 375169912728**Result** ✓ Passed**MOT #4** 2014-12-04 11:06**MOT test number** 579508934318**Result** ✓ Passed**Notice** Offside front tyre worn on inner edge.**MOT #3** 2013-12-10 15:07**MOT test number** 577214343369**Result** ✓ Passed**MOT #2** 2013-12-10 12:19**MOT test number** 216694843308**Result** ✗ Failed**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)



MOT #1	2013-01-10 11:26
MOT test number	387400013064
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 January 2025

✓  
**MOT**

**Expires:**  
14 January 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	14 January 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>GL59TXE</b>
Plate since	2019-09-28
Current registration	<b>GL59TXE</b>
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-01-12
Last registration	2024-01-15
Complete history	<a href="#">See info</a>



Registration #1	2010-01-12	29 mi
Registration #2	2013-01-10	19.956 mi
Registration #3	2013-12-10	26.468 mi
Registration #4	2013-12-10	26.468 mi
Registration #5	2014-12-04	29.585 mi
Registration #6	2015-12-08	33.425 mi
Registration #7	2016-12-09	37.237 mi
Registration #8	2017-12-08	41.813 mi
Registration #9	2018-01-01	41.813 mi
Registration #10	2018-01-01	41.813 mi
Registration #11	2018-01-01	41.813 mi
Registration #12	2018-01-01	41.813 mi
Registration #13	2018-01-01	41.813 mi
Registration #14	2018-01-01	41.813 mi
Registration #15	2018-01-01	41.813 mi
Registration #16	2018-01-01	41.813 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1450 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	768432