



report date: 2024-03-28

General information

Make	VOLVO
Model	V40 D2 R-DESIGN NAV
Colour	Blue
Year of manufacture	2015
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	280 Nm at 2.250 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	68.9 mpg
Consumption extra urban	85.6 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A







Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-05-04
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #8	2023-05-04 12:34
MOT test number	470957539506
Result	✓ Passed
Next expiry date	2024-05-04
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #7	2022-04-07 14:20
MOT test number	589019935195
Result	✓ Passed
Advice	Emissions too clean to test
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Offside Rear Tyre slightly damaged (5.2.3 (d) (ii))
Advice	Underbody covers fitted

**MOT #6** 2022-04-07 12:35**MOT test number** 193567748291**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Underbody covers fitted**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged (5.2.3 (d) (ii))**Advice** Emissions too clean to test**MOT #5** 2021-05-05 13:02**MOT test number** 966580974244**Result** ✓ Passed**MOT #4** 2021-01-19 08:25**MOT test number** 827163716397**Result** ✓ Passed**Advice** Undertrays fitted**MOT #3** 2019-11-04 09:01**MOT test number** 348107304253**Result** ✓ Passed**MOT #2** 2018-10-20 10:29**MOT test number** 385134948052**Result** ✓ Passed**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 20% imbalance (1.2.1 (b) (i))



MOT #1	2018-10-20 10:29
MOT test number	442467654725
Result	✗ Failed
<div><div>Advice</div>Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 20% imbalance (1.2.1 (b) (i))</div> <div><div>Pass with rectification</div>Nearside Front Position lamp not working (4.2.1 (a))</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
4 May 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	4 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-10-31
Last registration	2023-05-04
Complete history	See info



Registration #1	2015-10-31	7 mi
Registration #2	2018-10-20	44.298 mi
Registration #3	2018-10-20	44.298 mi
Registration #4	2019-11-04	58.181 mi
Registration #5	2021-01-19	77.557 mi
Registration #6	2022-05-20	95.277 mi
Registration #7	2022-05-20	95.277 mi
Registration #8	2022-05-20	95.277 mi
Registration #9	2022-05-20	95.277 mi
Registration #10	2023-05-04	102.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	2041 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1463 kg
Max. allowed weight	1980 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

1206934