






report date: 2024-03-28

General information

Make	ТОУОТА
Model	RAV-4 VVT-I XT-R
Colour	Grey
Year of manufacture	2005
Top speed	115 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	147 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	39.2 mpg
Consumption combined	32.5 mpg
CO2 emission	207 g/km
CO2 label	K



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-07-09

Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-03-08
MOT pass rate	90 %
MOT passed	18
Failed MOT tests	2
Total advice items	21
Total items failed	2

MOT #20	2024-03-05 09:47
MOT test number	225293265686
Result	✓ Passed
Next expiry date	2025-03-08
Advice Rear Brake pad(s) wearing thin Both N/S & O/S (1.1.13 (a) (ii))	

MOT #19	2023-03-09 11:37
MOT test number	690777184762
Result	✓ Passed
Advice Tyres are perished	
Minor Registration plate lamp inoperative in the case of multiple lamps or light	sources (4.7.1 (b) (i))

MOT #18	2022-07-20 08:58
MOT test number	320095197761
Result	✓ Passed
Advice Play in the n/s rear hub	
Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))	
Advice Offside headlamp output is poor	

CarCheck.co.uk page 3/13



YR05XCE

report date: 2024-03-28

MOT #17 2021-07-16 16:08

MOT test number 937936980082

MOT #16 2020-12-10 14:57

MOT test number 491123062051

Result

Passed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Exhaust has a minor leak of exhaust gases middle and rear joint (6.1.2 (a))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #15 2019-12-18 15:00

MOT test number 731680919033

Result
✓ Passed

Advice Items removed from driver's view prior to test

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #14 2019-12-18 15:00

MOT test number 367258306729

Result × Failed

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Pass with rectification

Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Items removed from driver's view prior to test

(b) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

CarCheck.co.uk page 4/13



MOT #13 2018-12-20 10:40

MOT test number 302799587590

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #12 2018-01-02 16:00

MOT test number 899884865724

Result ✓ Passed

MOT #11 2016-09-27 15:54

MOT test number 187659876166

Result ✓ Passed

MOT #10 2015-10-09 10:40

MOT test number 177369267174

Result \rightarrow Passed

MOT #9 2015-10-08 09:13

MOT test number 119733441393

Result X Failed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Nearside Front Shock absorber has a serious fluid leak (2.7.3)

MOT #8 2014-10-24 16:20

MOT test number 348467594262

Result ✓ Passed

CarCheck.co.uk page 5/13



YR05XCE

report date: 2024-03-28

MOT #7	2013-10-23 11:14
MOT test number	949796093226
Result	✓ Passed
MOT #6	2012-12-05 17:04
MOT test number	157290342322
Result	✓ Passed
MOT #5	2011-12-02 14:52
MOT test number	477666031361
Result	✓ Passed
Notice Front brake discs slightly pitted/corroded	
MOT #4	2010-12-08 12:22
MOT test number	114502640348
Result	✓ Passed
Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)	

MOT #3	2009-10-29 17:32
MOT test number	350472409350
Result	✓ Passed
MOT #2	2000 10 12 15:40

MOT #2	2008-10-13 15:48
MOT test number	720927988255
Result	✓ Passed

MOT #1	2008-03-26 08:42
MOT test number	672396388086
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	8 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e when mistery		
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.		ТΑ

	More info	>
Plate changes See in this check if this TOYOTA had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-04-08
Last registration	2024-03-05
Complete history	See info



Registration #1	2005-04-08	6 mi
Registration #2	2008-03-26	35.980 mi
Registration #3	2008-10-13	41.206 mi
Registration #4	2009-10-29	46.629 mi
Registration #5	2010-12-08	53.390 mi
Registration #6	2011-12-02	60.741 mi
Registration #7	2012-12-05	67.777 mi
Registration #8	2013-10-23	74.104 mi
Registration #9	2014-10-24	82.570 mi
Registration #10	2015-10-08	92.429 mi
Registration #11	2015-10-09	92.429 mi
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		9.777 es
Registration #18		11.777 es
Registration #19		9.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es

More info >

CarCheck.co.uk page 12/13



YR05XCE

report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1785 mm
Height	1685 mm
Length	3870 mm
Wheel base	2280 mm
Kerb weight	1325 kg
Max. allowed weight	1685 kg

Additional information

Fuel tank capacity	57 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	1AZ1815993

CarCheck.co.uk page 13/13