



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	AVENSIS D-4D T2
Colour	Silver
Year of manufacture	2011
Top speed	124 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	310 Nm at 1.800 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-09-25
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-27
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	23
Total items failed	15

MOT #162023-11-16 14:17

MOT test number180914717088

Result✓ Passed

Next expiry date2024-11-27

- Advice

Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice

Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive Slightly corroded. (5.3.6 (a) (i))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge Badly worn on inner and outer edges. (5.2.3 (e))
- Advice

Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice

Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive Slightly corroded. (5.3.6 (a) (i))
- Advice

Nearside Rear Bumper damaged and taped up.

**MOT #15**

2023-11-15 12:54

**MOT test number**

202168672202

**Result****✗ Failed**

**Advice** Offside Front Tyre worn close to legal limit/worn on edge Badly worn on inner and outer edges. (5.2.3 (e))

**Fail** Horn not working (7.7 (a))

**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive Slightly corroded. (5.3.6 (a) (i))

**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Advice** Nearside Rear Bumper damaged and taped up.

**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**Minor** Nearside Front Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive Slightly corroded. (5.3.6 (a) (i))

**Fail** Nearside Front Side repeater not working (4.4.1 (a) (ii))

**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #14**

2022-11-28 13:47

**MOT test number**

971825099895

**Result****✓ Passed**

**Advice** Bumper mountings corroded but not likely to become detached Both front and rear with slight damage to both (6.1.4 (a) (i))

**MOT #13**

2022-11-23 10:33

**MOT test number**

909306980479

**Result**

✗ Failed

**Fail** Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**Advice** Bumper mountings corroded but not likely to become detached Both front and rear with slight damage to both (6.1.4 (a) (i))**Fail** Front Windscreen washer not working (3.5 (a))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #12**

2021-11-25 17:05

**MOT test number**

296153066628

**Result**

✓ Passed

**MOT #11**

2020-11-17 09:04

**MOT test number**

269048229541

**Result**

✓ Passed

**MOT #10**

2019-11-26 15:17

**MOT test number**

618763724268

**Result**

✓ Passed

**MOT #9** 2018-10-11 13:25**MOT test number** 419772926153**Result** ✓ Passed**MOT #8** 2017-09-07 11:05**MOT test number** 650946661430**Result** ✓ Passed**MOT #7** 2016-09-09 14:12**MOT test number** 971817017364**Result** ✓ Passed**MOT #6** 2016-09-09 14:12**MOT test number** 298615333608**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #5** 2016-03-15 14:29**MOT test number** 602777454293**Result** ✓ Passed**MOT #4** 2015-09-10 15:06**MOT test number** 994491351632**Result** ✓ Passed**MOT #3** 2015-03-14 12:05**MOT test number** 418383975093**Result** ✓ Passed



MOT #2	2014-10-23 15:12
MOT test number	809336094251
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components

MOT #1	2014-10-23 14:26
MOT test number	427566394280
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Notice	Engine covers fitted obscuring some components in the engine bay
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Notice	Under-trays fitted obscuring some underside components



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
27 November 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	185
<b>MOT expiry date</b>	27 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	<b>FL61HVK</b>
Plate since	2024-03-29
Current registration	<b>FL61HVK</b>
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-11-30
Last registration	2023-11-16
Complete history	<a href="#">See info</a>



Registration #1	2011-11-30	18 mi
Registration #2	2014-10-23	39.528 mi
Registration #3	2014-10-23	39.528 mi
Registration #4	2015-03-14	41.275 mi
Registration #5	2015-09-10	47.146 mi
Registration #6	2016-03-15	51.202 mi
Registration #7	2016-09-09	57.093 mi
Registration #8	2016-09-09	57.093 mi
Registration #9	2017-09-07	64.729 mi
Registration #10	2018-05-20	75.377 mi
Registration #11	2018-05-20	75.377 mi
Registration #12	2018-05-20	75.377 mi
Registration #13	2018-05-20	75.377 mi
Registration #14	2018-05-20	75.377 mi
Registration #15	2018-05-20	75.377 mi
Registration #16	2018-05-20	75.377 mi
Registration #17	2018-05-20	75.377 mi
Registration #18	2018-05-20	75.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	53%
Safety systems	86%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1480 mm
Length	4695 mm
Wheel base	2700 mm
Kerb weight	1410 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1AD5590401