






report date: 2024-03-28

#### General information

Make	RENAULT
Model	SCENIC DYNAMIQUE TOMTOM DCI
Colour	Red
Year of manufacture	2013
Top speed	112 mph
0 - 60 mph	12.3 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/12



# Internet history

#### Entry 1

Date 2021-06-04

Pictures 31

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-17
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	8
Total items failed	6

MOT #14	2023-10-18 08:43
MOT test number	858168944393
Result	✓ Passed
Next expiry date	2024-10-17

MOT #13	2023-10-18 08:43
MOT test number	571753571623
Result	<b>X</b> Failed
Pass with rectification (ii))	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b)

MOT #12	2022-10-03 11:00
MOT test number	561395367971
Result	✓ Passed

MOT #11	2021-10-13 10:02
MOT test number	266632433665
Result	<b>√</b> Passed
Advice Rear Brake disc worn, pitted or scored, but not seriously wea	akened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-28

**MOT #10** 2021-10-13 10:02

**MOT test number** 227942662819

**Result** X Failed

**Pass with rectification** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #9 2020-10-02 09:49

**MOT test number** 825082680731

**Result** 
✓ Passed

MOT #8 2020-10-01 09:57

**MOT test number** 507295308797

**Result** X Failed

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 205/60/16 (5.2.3 (d) (i))

MOT #7 2019-10-02 11:33

MOT test number 781157295511

Result 

Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6 2019-10-02 09:13

MOT test number 311682293755

Result X Failed

**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5 2018-09-26 15:35

**MOT test number** 787541862338

**Result** 
✓ Passed

MOT #4 2018-09-26 09:56

MOT test number 362984609609

**Result** ★ Failed

**Fail** Offside Outer Prop shaft joint constant velocity boot no longer prevents the ingress of dirt boot clip missing (6.1.7 (g) (ii))

MOT #3 2017-09-29 10:46

**MOT test number** 174370507929

**Result** 
✓ Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** 

MOT #2 2016-10-06 12:59

MOT test number 806716186360

MOT #1 2016-02-23 12:36

MOT test number 622187439134

Result 

Passed

Advice Nearside Front Side repeater damaged, but still visible from a reasonable distance door mirror

(1.4.A.2e)

**Advice** Offside Front Side repeater damaged, but still visible from a reasonable distance door mirror (1.4.A.2e)

CarCheck.co.uk page 5/12



#### Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	17 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



faste since

DY13CZN

report date: 2024-03-28

More info >

# Owner history For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this RENAULT had different number plates. ober of plates

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-04-15
Last registration	2023-10-18
Complete history	See info



Registration #1	2013-04-15	7 mi
Registration #2	2016-02-23	29.975 mi
Registration #3	2016-10-06	32.010 mi
Registration #4	2017-09-29	48.818 mi
Registration #5	2018-09-26	65.700 mi
Registration #6	2018-09-26	65.700 mi
Registration #7	2019-10-02	81.364 mi
Registration #8	2019-10-02	81.364 mi
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		11.777 mi
Registration #14		11.777 es
Registration #15		11.777 mi
Registration #16		10.777 au

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1845 mm
Height	1640 mm
Length	4366 mm
Wheel base	2697 mm
Kerb weight	1432 kg
Max. allowed weight	1964 kg

# Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pag	je 12/12

Number of axles2Engine numberD128515