





report date: 2024-03-29

General information

Make	FORD
Model	C-MAX ZETEC
Colour	Grey
Year of manufacture	2013
Top speed	112 mph
0 - 100 km/h	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 kW / 125 HP / 103 BHP
Max. torque	159 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/13



FE63OVY report date: 2024-03-29

Internet history

Entry 3

Date 2022-01-14

Pictures 9

Listing price <u>View report</u>










source: autotrader.co.uk

Entry 2

Date	2021-12-17
------	------------

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-10-08


Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



FE63OVY report date: 2024-03-29

MOT history

MOT expiry date	2024-06-26
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	21
Total items failed	6

MOT #11		2023-06-14 10:58
MOT test	number	896787947270
Result		✓ Passed
Next expi	ry date	2024-06-26
Advice Tyre worn close to legal limit/worn on edge Both Rear (5.2.3 (e))		
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice	Vehicle Has Covers Fitted Unable To See Certain Testable Items	

MOT #10		2022-06-27 17:01
MOT test	number	234781988288
Result		✓ Passed
Advice	Vehicle has covers fitted unable to see certain testable items	
Advice	Exhaust System Is Slightly Corroded	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #9	2022-06-27 13:58
MOT test number	107333430286
Result	× Failed
Fail Offside Front Headlamp insecure (4.1.1 (c))	
Advice Vehicle has covers fitted unable to see certain testable items	
Fail Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))	
Fail Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Exhaust System Is Slightly Corroded	
Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #8	2021-06-14 08:09
MOT test number	910846655792
Result	✓ Passed
MOT #7	2020-01-20 14:45
MOT test number	739845065421
Result	✓ Passed
Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Vehicles internal headlight adjuster altered to recheck lights low	

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #6 2019-01-02 11:39 **MOT** test number 780458869535 Result ✓ Passed **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing and wearing inner edge (4mm in tread) (5.2.3 (d) (ii)) **Advice** Under-trays fitted (restricted view) **Advice** Rear Brake disc worn, but not excessively nearside and offside (1.1.14 (a) (i)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii)) **Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) Rear All direction indicators slightly discoloured nearside and offside (4.4.3 (a)) **Advice Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #5

MOT test number

Result

MOT test number

304498286792

Result

✓ Passed

MOT #4

2017-01-24 08:21

MOT test number

873610252615

Result

✓ Passed

Advice

Nearside Rear Shock absorber has a light misting of oil (2.7.3)

MOT test number

Result

Nearside Stop lamp not working (1.2.1b)

Advice

Nearside Rear Shock absorber has a light misting of oil (2.7.3)

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #2	2016-07-25 11:42
MOT test number	575035210653
Result	✓ Passed
MOT #1	2016-07-25 10:44
MOT test number	216430098708
Result	X Failed
Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)	

CarCheck.co.uk page 6/13



FE63OVY report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	26 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



faste since

FE63OVY

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this FORD had different number plates.

CarCheck.co.uk page 10/13



FE630V

report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-09-25
Last registration	2023-06-14
Complete history	See info



Registration #1	2013-09-25	17 mi
Registration #2	2016-07-25	25.679 mi
Registration #3	2016-07-25	25.679 mi
Registration #4	2017-01-23	28.344 mi
Registration #5	2017-01-24	28.344 mi
Registration #6	2017-12-29	32.117 mi
Registration #7	2019-01-02	36.009 mi
Registration #8	2020-01-20	40.187 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 ms

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	92%
Children	83%
Pedestrian	50%
Safety systems	71%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1626 mm
Length	4380 mm
Wheel base	2850 mm
Kerb weight	1374 kg
Max. allowed weight	1860 kg

Additional information

Fuel tank capacity	55 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2

Engine number DG20614