



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	SLK SLK 200 KOMPRESSOR
Colour	Silver
Year of manufacture	2010
Top speed	155 mph
0 - 60 mph	7.9 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.9 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.5 mpg
CO2 emission	192 g/km
CO2 label	J





Internet history

Entry 2



Date	2022-02-27
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-12-07
Pictures	19
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2024-02-16
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	29
Total items failed	0

MOT #13 2023-02-17 15:07

MOT test number 342995486316

Result ✓ Passed

Next expiry date 2024-02-16

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear subframe undersealed/painted
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pipe corroded, covered in grease or other material pipes (1.1.11 (c))

MOT #12 2023-02-10 11:49

MOT test number 152573281501

Result ✗ Failed

- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Rear Brake pipe corroded, covered in grease or other material pipes (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Rear Sub-frame corroded and seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))

**MOT #11** 2022-02-10 18:34**MOT test number** 461197799609**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #10** 2021-06-24 11:55**MOT test number** 945275434432**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**MOT #9** 2021-06-03 10:58**MOT test number** 377468061019**Result** ✗ Failed**MAJOR** Offside Rear fog lamp not working (4.5.1 (a) (ii))**MAJOR** Hazard warning lamps inoperative (4.4.1 (e))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Offside Front Direction indicator not working (4.4.1 (a) (ii))**MAJOR** Stop lamp(s) not working Centre high level (4.3.1 (a) (ii))**MAJOR** Offside Rear Direction indicator not working (4.4.1 (a) (ii))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Nearside Front Direction indicator not working (4.4.1 (a) (ii))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #8** 2020-06-10 13:51**MOT test number** 482124364082**Result** ✓ Passed**Advice** Slight play in both inner steering rack joints**MOT #7** 2019-06-05 15:40**MOT test number** 519960887737**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm ball joint has slight play very slight play (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-06-09 08:34**MOT test number** 647820606128**Result** ✓ Passed**MOT #5** 2017-06-10 07:59**MOT test number** 180985077652**Result** ✓ Passed**Advice** Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)**Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c)**MOT #4** 2016-06-21 09:57**MOT test number** 654690572196**Result** ✓ Passed**MOT #3** 2015-07-09 15:49**MOT test number** 155380395102**Result** ✓ Passed



MOT #2	2014-07-03 13:14
MOT test number	507634284148
Result	✓ Passed

MOT #1	2013-07-08 14:01
MOT test number	856869683164
Result	✓ Passed

Notice Under-trays fitted obscuring some underside components



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 NG10KXX
Plate since	2019-06-29
Current registration	 NG10KXX
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-07-26
Last registration	2023-02-17
Complete history	See info



Registration #1	2010-07-26	9 mi
Registration #2	2013-07-08	34.062 mi
Registration #3	2014-07-03	49.373 mi
Registration #4	2015-07-09	64.520 mi
Registration #5	2016-06-21	73.854 mi
Registration #6	2017-06-10	77.922 mi
Registration #7	2018-06-09	82.365 mi
Registration #8	2019-06-05	85.492 mi
Registration #9	2020-06-05	88.520 mi
Registration #10	2021-06-05	91.548 mi
Registration #11	2022-06-05	94.576 mi
Registration #12	2023-02-17	97.604 mi
Registration #13	2023-02-17	100.632 mi
Registration #14	2023-02-17	103.660 mi
Registration #15	2023-02-17	106.688 mi
Registration #16	2023-02-17	109.716 mi

More info >



Dimensions & weight

Width	2012 mm
Height	1296 mm
Length	4103 mm
Wheel base	2430 mm

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27195431315359