





report date: 2024-03-29

## General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Grey
Year of manufacture	2008
Top speed	104 mph
0 - 60 mph	13.9 seconds
Gearbox	4 speed automatic

### Engine & fuel consumption

Power	95 BHP
Max. torque	125 Nm at 3.200 rpm
Engine capacity	1.399 сс
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/13



## Internet history

#### Entry 1

Date 2021-07-10

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-12-27
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	8
Total items failed	9

MOT #17	2023-12-28 15:09
MOT test number	247171329510
Result	✓ Passed
Next expiry date	2024-12-27

MOT #16	2021-11-24 13:19
MOT test number	411122513905
Result	✓ Passed

MOT #15	5	2021-11-17 15:52
MOT tes	t number	326646132306
Result		<b>×</b> Failed
Fail	Front Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	

MOT #14		2020-11-25 11:31
MOT test i	number	246385185688
Result		✓ Passed
Advice	Central Rear Upper Stop lamp(s) non-obligatory stop lamp not working	(4.3.1 (a) (ii))

CarCheck.co.uk page 3/13



Result

EJ58KLC report date: 2024-03-29

✓ Passed

**MOT #13** 2020-11-25 11:31 **MOT** test number 409791870458 Result × Failed **Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2(c))**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Central Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #12

MOT test number

Result

Advice Central Upper stop light inoperative.

Advice Brake pedal anti-slip pad wear.

Advice Power steering pump drive belt cracking.

MOT #11	2018-10-24 11:47
MOT test number	781302344749
Result	<b>✓</b> Passed
MOT #10	2017-11-30 10:11
MOT test number	788576725528

MOT #9	2016-11-11 15:50
MOT test number	842126341997

CarCheck.co.uk page 4/13



MOT #8 2016-11-11 12:51

**MOT test number** 461426375312

**Result** X Failed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #7 2015-11-10 10:20

MOT test number 177954801862

Result \( \sqrt{Passed} \)

MOT #6 2014-11-07 10:18

**MOT test number** 109891814333

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2014-11-07 10:18

MOT test number 185831014326

**Result** X Failed

**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2013-11-26 14:26

**MOT test number** 936850733327

**Result** ✓ Passed

**MOT #3** 2012-11-05 11:25

**MOT test number** 686430012334

**Result** 
✓ Passed

CarCheck.co.uk page 5/13



MOT #2 2011-11-23 09:43

**MOT test number** 855107921385

**Result** ✓ Passed

MOT #1 2011-11-23 09:43

MOT test number 199367321340

Result X Failed

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively

(8.2.2)

**Pass with rectification** Nearside Headlamp aim too low (1.8)

CarCheck.co.uk page 6/13



## Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	27 December 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



### Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
***************************************	
HARMAN AND AND AND AND AND AND AND AND AND A	
***************************************	
THE STATE OF THE S	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	IK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



## Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-11-28
Last registration	2023-12-28
Complete history	See info



Registration #1	2008-11-28	24 mi
Registration #2	2011-11-23	12.092 mi
Registration #3	2012-11-05	17.423 mi
Registration #4	2013-11-26	21.989 mi
Registration #5	2014-11-07	26.088 mi
Registration #6	2015-11-10	30.445 mi
Registration #7	2016-11-11	34.111 mi
Registration #8	2016-11-11	34.116 mi
Registration #9	2017-11-30	37.167 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		10.777 esc

More info >

CarCheck.co.uk page 12/13



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	1055 kg
Max. allowed weight	1540 kg

## Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13