



report date: 2025-01-14

General information

Make	MINI
Model	COUNTRYMAN COOPER AUTO COOPER
Colour	Blue
Year of manufacture	2011
Top speed	113 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.2 mpg
CO2 emission	168 g/km
CO2 label	H






Internet history

Entry 2

Date	2022-01-19
Pictures	20
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-01-18
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2026-01-24
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	14
Total items failed	0

MOT #14	2025-01-18 12:52
MOT test number	521430934326
Result	✓ Passed
Next expiry date	2026-01-24
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2024-01-20 13:17
MOT test number	391508969844
Result	✓ Passed

MOT #12	2023-01-07 12:50
MOT test number	758998526551
Result	✓ Passed

MOT #11	2022-01-25 10:01
MOT test number	974882629959
Result	✓ Passed



MOT #10 2021-05-07 14:02

MOT test number 711118165115

Result ✓ Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #9 2020-10-15 08:09

MOT test number 490534321775

Result ✓ Passed

Advice Child Seat fitted not allowing full inspection of adult belt

MOT #8 2020-10-14 09:07

MOT test number 660741164128

Result ✗ Failed

MAJOR Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Child Seat fitted not allowing full inspection of adult belt

MOT #7 2019-05-14 08:14

MOT test number 499397297933

Result ✓ Passed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #6 2019-05-10 13:01

MOT test number 601135206354

Result ✗ Failed

DANGEROUS Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))



MOT #5 2018-05-14 09:45

MOT test number 104393489036

Result ✓ Passed

MOT #4 2017-03-07 14:22

MOT test number 252643945219

Result ✓ Passed

MOT #3 2016-03-08 17:07

MOT test number 605524235855

Result ✓ Passed

- Advice** Nearside child seat fitted so belt not tested
- Advice** Offside Rear engine oil leak noted
- Advice** Offside Rear child seat fitted therefore belt not tested

MOT #2 2015-02-20 12:42

MOT test number 545621955062

Result ✓ Passed

- Notice** Offside front tyre worn bald on outer edge.

MOT #1 2014-03-11 11:08

MOT test number 236110474002

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
24 January 2026

Tax status	Valid until 1 April
Days left	46
MOT expiry date	24 January 2026
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	EXAMPLE
Category	EXAMPLE
Type	EXAMPLE



Damage 2

Date	EXAMPLE
Category	EXAMPLE
Type	EXAMPLE



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	LN110OB
Plate since	2015-05-29
Current registration	LN110OB
Plate since	2015-05-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-03-01
Last registration	2025-01-18
Complete history	See info



Registration #1	2011-03-01	28 mi
Registration #2	2014-03-11	13.655 mi
Registration #3	2015-02-20	16.369 mi
Registration #4	2016-03-08	19.366 mi
Registration #5	2017-03-07	21.875 mi
Registration #6	2018-05-14	23.676 mi
Registration #7	2019-05-10	26.344 mi
Registration #8	2019-05-14	26.344 mi
Registration #9	2020-10-14	31.003 mi
Registration #10	2020-10-14	31.003 mi
Registration #11	2020-10-14	31.003 mi
Registration #12	2020-10-14	31.003 mi
Registration #13	2020-10-14	31.003 mi
Registration #14	2020-10-14	31.003 mi
Registration #15	2020-10-14	31.003 mi
Registration #16	2020-10-14	31.003 mi
Registration #17	2020-10-14	31.003 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1295 kg
Max. allowed weight	1765 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	A5171989