



UK

PEIIXKV

report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO GP
Colour	Blue
Year of manufacture	2011
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

**MOT history**

MOT expiry date	2025-02-07
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	42
Total items failed	1

MOT #12	2024-02-05 11:02
MOT test number	310446504265
Result	✓ Passed
Next expiry date	2025-02-07
Advice	Oil leak, but not excessive sump (8.4.1 (a) (i))
Advice	Exhaust has a minor leak of exhaust gases rear silencer (6.1.2 (a))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #11	2023-02-08 16:50
MOT test number	646881672806
Result	✓ Passed

MOT #10	2022-02-02 14:12
MOT test number	174494533808
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))



MOT #9	2021-02-08 12:08
MOT test number	123470813140
Result	✓ Passed

MOT #8	2020-07-29 09:23
MOT test number	681433861077
Result	✓ Passed

- Advice** Offside Rear Shock absorbers has slight external damage to the casing CORRODED (5.3.2 (b))
- Advice** Front Exhaust has a minor leak of exhaust gases FLEX (6.1.2 (a))
- Advice** Oil leak, but not excessive GEARBOX OIL LEAK (8.4.1 (a) (i))
- Advice** Nearside Rear Brake cable damaged but not to excess (1.1.15 (a))
- Advice** BOOT WONT OPEN FROM OUTSIDE ABLE TO OPEN BOOT FROM INSIDE TO PERFORM INSPECTION
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing CORRODED (5.3.2 (b))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement
SUSPESION ARM REAR MOUNTING BUSH (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive SUMP POURES. WANTS NEW SUMP (8.4.1 (a) (i))
- Advice** Offside Front Lower Coil spring worn COIL RUBBING AGAINST BASE PLATE UPPSIDE DOWN OR
LOWER COIL FATIUGED (5.3.1 (b) (i))
- Advice** Offside Rear Brake cable damaged but not to excess (1.1.15 (a))
- Advice** Tyre slightly damaged/cracking or perishing ALL TYRES CRACKING (5.2.3 (d) (ii))

**MOT #7** 2019-08-16 14:17**MOT test number** 791819880258**Result** ✓ Passed**Advice** Nearside Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #6** 2018-08-18 15:24**MOT test number** 748967693090**Result** ✓ Passed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Rear Exhaust has a minor leak of exhaust gases BACK BOX OUTER SKIN (6.1.2 (a))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #5**

2018-08-18 09:42

MOT test number

572308141962

Result**✗ Failed**

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Rear Exhaust has a minor leak of exhaust gases BACK BOX OUTER SKIN (6.1.2 (a))

MOT #4

2017-08-16 08:57

MOT test number

192913744169

Result**✓ Passed**

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front front brake fluctuating, but not excessively (3.7.B.3)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front front brake fluctuating, but not excessively (3.7.B.3)
- Advice** Rear exhaust box corroded
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)

MOT #3

2016-08-23 08:23

MOT test number

607581972300

Result**✓ Passed**



MOT #2	2015-04-17 14:25
MOT test number	157387505182
Result	✓ Passed
<div>NoticeItems removed from driver's view prior to test</div>	

MOT #1	2014-04-16 08:54
MOT test number	269296904474
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
7 February 2025

Tax status	Valid until 1 October
Days left	155
MOT expiry date	7 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	PE11XKV
Plate since	2019-03-29
Current registration	PE11XKV
Plate since	2019-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-04-27
Last registration	2024-02-05
Complete history	See info



Registration #1	2011-04-27	19 mi
Registration #2	2014-04-16	14.879 mi
Registration #3	2015-04-17	23.135 mi
Registration #4	2016-08-23	36.706 mi
Registration #5	2017-08-16	43.114 mi
Registration #6	2018-08-18	45.844 mi
Registration #7	2018-08-18	45.844 mi
Registration #8	2019-05-20	55.277 mi
Registration #9	2019-05-20	55.277 mi
Registration #10	2019-05-20	55.277 mi
Registration #11	2019-05-20	55.277 mi
Registration #12	2019-05-20	55.277 mi
Registration #13	2019-05-20	55.277 mi
Registration #14	2019-05-20	55.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	6332630