



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D DRIVE S
Colour	Blue
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	118 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-24
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-04
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	48
Total items failed	0

MOT #14	2023-08-05 11:05
MOT test number	276749687260
Result	✓ Passed
Next expiry date	2024-08-04
Advice	Front Tyre worn close to legal limit/worn on edge N/s and o/s balding inner edges very close to cord (5.2.3 (e))
Advice	Rear Tyre slightly damaged/cracking or perishing N/s and o/s edges cracking but unable to see cord or play (5.2.3 (d) (ii))

**MOT #13**

2022-07-25 09:37

**MOT test number**

341657639426

**Result**

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake lining(s) wearing thin On about 2mm (1.1.13 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin On about 2mm (1.1.13 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords Sidewall (5.2.3 (d) (i))

**MOT #12**

2021-07-26 10:23

**MOT test number**

969870496507

**Result**

✓ Passed



MOT #11

2020-10-06 15:46

MOT test number

847550298383

Result		✓ Passed
Minor	Offside Rear Brake hose slightly damaged Reinforcer rubber split (1.1.12 (b) (i))	
Advice	Oil leak, but not excessive Slight leak engine area (8.4.1 (a) (i))	
Minor	Nearside Front Windscreen wiper blade defective Split (3.4 (b) (i))	
Advice	Nearside Front Tyre wearing on inner tread	
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords Cut on outer wall (5.2.3 (d) (i))	
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
Minor	Nearside Rear Brake hose slightly damaged Reinforcer rubber split (1.1.12 (b) (i))	
Advice	Offside Front Tyre worn bald inner tread	
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	

**MOT #10**

2020-10-06 11:03

**MOT test number**

587630642764

**Result****✗ Failed**

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Minor** Offside Rear Brake hose slightly damaged Reinforcer rubber split (1.1.12 (b) (i))

**Advice** Nearside Front Tyre wearing on inner tread

**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords Cut on outer wall (5.2.3 (d) (i))

**Minor** Nearside Front Windscreen wiper blade defective Split (3.4 (b) (i))

**MAJOR** Front Windscreen washer not working (3.5 (a))

**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Offside Front Tyre worn bald inner tread

**MAJOR** Offside Front Headlamp aim not tested (4.1.2 (b))

**Minor** Nearside Rear Brake hose slightly damaged Reinforcer rubber split (1.1.12 (b) (i))

**Advice** Oil leak, but not excessive Slight leak engine area (8.4.1 (a) (i))

**MOT #9**

2019-04-03 14:37

**MOT test number**

205914878943

**Result****✓ Passed**

**MOT #8** 2019-04-02 11:13**MOT test number** 200995114670**Result** ✗ Failed**MAJOR** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**DANGEROUS** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Minor** Offside Rear Position lamp light intensity obviously reduced (4.2.3 (a) (i))**MAJOR** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #7** 2018-03-27 13:31**MOT test number** 956724677803**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**MOT #6** 2017-03-28 13:45**MOT test number** 729590049616**Result** ✓ Passed**MOT #5** 2016-03-18 12:37**MOT test number** 768063598796**Result** ✓ Passed**MOT #4** 2015-03-10 16:42**MOT test number** 836329965090**Result** ✓ Passed



<b>MOT #3</b>	2014-04-02 15:27
---------------	------------------

<b>MOT test number</b>	705942194038
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	---

<b>MOT #2</b>	2013-04-10 16:41
---------------	------------------

<b>MOT test number</b>	159120903165
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2012-04-03 10:20
---------------	------------------

<b>MOT test number</b>	939524692052
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Notice</b>	Child seat fitted not allowing full inspection of adult belt
---------------	--

<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
4 August 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	4 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history


Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-04-08
Last registration	2023-08-05
Complete history	<a href="#">See info</a>



Registration #1	2009-04-08	9 mi
Registration #2	2012-04-03	23.745 mi
Registration #3	2013-04-10	30.993 mi
Registration #4	2014-04-02	38.883 mi
Registration #5	2015-03-10	45.733 mi
Registration #6	2016-03-18	54.008 mi
Registration #7	2017-03-28	64.500 mi
Registration #8	2018-03-27	75.181 mi
Registration #9	2019-03-27	85.862 mi
Registration #10	2020-03-27	96.543 mi
Registration #11	2021-03-27	107.224 mi
Registration #12	2022-03-27	117.905 mi
Registration #13	2023-03-27	128.586 mi
Registration #14	2024-03-27	139.267 mi
Registration #15	2025-03-27	149.948 mi
Registration #16	2026-03-27	160.629 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1408 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number

538565