



report date: 2024-03-29

## General information

Make	VOLVO
Model	S40 D DRIVE SE LUX
Colour	Black
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B








Internet history

Entry 1

Date	2021-07-19
Pictures	30
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-06-29
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	15
Total items failed	2

MOT #13	2023-06-06 12:58
MOT test number	925678959925
Result	✓ Passed
Next expiry date	2024-06-29
Advice	Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))

MOT #12	2023-06-06 10:20
MOT test number	412806654152
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))
MAJOR	Nearside Headlamp aim too low (4.1.2 (a))
Advice	Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

MOT #11	2022-06-24 08:29
MOT test number	539856801988
Result	✓ Passed

MOT #10	2021-06-16 10:16
MOT test number	922710244612
Result	✓ Passed

**MOT #9** 2020-06-30 15:16**MOT test number** 319945202472**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #8** 2019-05-10 10:25**MOT test number** 873835541358**Result** ✓ Passed**MOT #7** 2018-05-08 08:29**MOT test number** 713343159815**Result** ✓ Passed**MOT #6** 2017-05-11 08:02**MOT test number** 700400575345**Result** ✓ Passed**Advice** Both front tyres heavily cracked**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2016-05-16 16:06**MOT test number** 429161942835**Result** ✓ Passed**MOT #4** 2016-05-16 11:42**MOT test number** 773371769750**Result** ✗ Failed**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #3** 2015-08-29 10:55**MOT test number** 905476154155**Result** ✓ Passed**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Rear reflector slightly damaged but function not impaired (1.5.1c)**MOT #2** 2014-08-28 16:41**MOT test number** 376430044454**Result** ✓ Passed**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2013-09-13 15:24**MOT test number** 756026953249**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
29 June 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	29 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>DK60TXY</b>
Plate since	2019-09-29
Current registration	<b>DK60TXY</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-10-27
Last registration	2023-06-06
Complete history	<a href="#">See info</a>



Registration #1	2010-10-27	9 mi
Registration #2	2013-09-13	22.323 mi
Registration #3	2014-08-28	30.312 mi
Registration #4	2015-08-29	37.997 mi
Registration #5	2016-05-16	42.861 mi
Registration #6	2016-05-16	42.861 mi
Registration #7	2017-05-11	55.488 mi
Registration #8	2018-05-08	64.067 mi
Registration #9	2019-05-08	75.377 mi
Registration #10	2020-05-08	85.377 mi
Registration #11	2021-05-08	95.377 mi
Registration #12	2022-05-08	105.377 mi
Registration #13	2023-05-08	115.377 mi
Registration #14	2024-05-08	125.377 mi
Registration #15	2025-05-08	135.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1260602