



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	EXPERT L2 H1 HDI LWB P/V
Colour	Blue
Year of manufacture	2009
Top speed	99 mph
0 - 60 mph	13.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	300 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	38.2 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2025-01-16
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	47
Total items failed	8

MOT #17 2023-12-18 10:30

MOT test number 297057158554

Result ✓ Passed

Next expiry date 2025-01-16

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer shoulder (5.2.3 (e))
- Minor** Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))

MOT #16 2023-12-18 10:30

MOT test number 582669758462

Result ✗ Failed

- Pass with rectification** Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer shoulder (5.2.3 (e))
- Minor** Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #15** 2023-01-03 10:51**MOT test number** 596721707703**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2023-01-03 10:51**MOT test number** 606610853535**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Pass with rectification** Rear fog lamp not working (4.5.1 (a) (ii))**MOT #13** 2022-01-17 14:49**MOT test number** 230955320861**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #12** 2022-01-12 13:49**MOT test number** 798967160496**Result** ✗ Failed**MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))**MAJOR** Windscreen washer not working (3.5 (a))**MAJOR** Exhaust system insecure (6.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #11**

2020-09-22 09:26

MOT test number

756583780180

Result

✓ Passed

Advice

Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement D-bush (5.3.4 (a) (i))

MOT #10

2019-04-18 12:01

MOT test number

272070381642

Result

✓ Passed

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened Lipped (1.1.14 (a) (ii))

Minor

Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated Or damaged (6.1.7 (g) (i))

Advice

Nearside Front Lower Oil leak, but not excessive Engine (8.4.1 (a) (i))

MOT #9

2019-04-17 10:37

MOT test number

158140055359

Result

✗ Failed

DANGEROUS

Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MAJOR

Brake lever has insufficient reserve travel In cab (1.1.2 (a))

MAJOR

Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Minor

Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated Or damaged (6.1.7 (g) (i))

Advice

Nearside Front Lower Oil leak, but not excessive Engine (8.4.1 (a) (i))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened Lipped (1.1.14 (a) (ii))

MAJOR

Offside Rear Parking brake inoperative on one side (1.4.1 (a))

MAJOR

Offside Front Position lamp not working (4.2.1 (a))

MAJOR

Nearside Front Anti-roll bar pin or bush excessively worn D-bush has excessive movement (5.3.4 (a) (i))

**MOT #8**

2018-03-28 13:00

MOT test number

634572054569

Result

✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Oil leak Engine**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7**

2018-03-28 09:05

MOT test number

904833288267

Result

✗ Failed

Fail Offside Rear rear parking brake recording little or no effort (3.7.B.6a)**Advice** Oil leak Engine**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #6**

2017-03-29 11:56

MOT test number

547040928890

Result

✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2017-03-27 13:07**MOT test number** 354146184004**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Lower Suspension arm has excessive play in a pin/bush (2.4.G.2)**MOT #4** 2016-04-14 15:48**MOT test number** 364919814416**Result** ✓ Passed**Advice** Nearside Front tyre is worn on the inner and outer edges**Advice** Offside Front tyre is worn on the inner and outer edges**MOT #3** 2014-11-21 11:32**MOT test number** 875815824316**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #2** 2013-11-27 14:25**MOT test number** 115891533378**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #1** 2012-07-09 12:33**MOT test number** 547651392183**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
16 January 2025

Tax status	Valid until 1 August
-------------------	----------------------

Days left	94
------------------	----

MOT expiry date	16 January 2025
------------------------	-----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-06-19
Last registration	2023-12-18
Complete history	See info



Registration #1	2009-06-19	21 mi
Registration #2	2012-07-09	59.367 mi
Registration #3	2013-11-27	86.907 mi
Registration #4	2014-11-21	108.211 mi
Registration #5	2016-04-14	128.205 mi
Registration #6	2017-03-27	136.017 mi
Registration #7	2017-03-29	136.112 mi
Registration #8	2018-03-28	143.122 mi
Registration #9	2018-03-28	143.123 mi
Registration #10	2019-03-28	151.217 mi
Registration #11	2019-03-28	151.217 mi
Registration #12	2019-03-28	151.217 mi
Registration #13	2019-03-28	151.217 mi
Registration #14	2019-03-28	151.217 mi
Registration #15	2019-03-28	151.217 mi
Registration #16	2019-03-28	151.217 mi
Registration #17	2019-03-28	151.217 mi
Registration #18	2019-03-28	151.217 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2194 mm
Height	1980 mm
Length	5135 mm
Kerb weight	1744 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	DYXA4008289