





#### General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	White
Year of manufacture	2011
Top speed	97 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

D	CO DUD
Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg
CO2 emission	123 g/km
CO2 label	D







am

# Internet history

Entry 1		
Date	2021-06-20	
Pictures	37	
Listing price	View report	



source: autotrader.co.uk



# MOT history

MOT expiry date	2024-06-15
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	17
Total items failed	11

MOT #15		2023-06-05 10:23
MOT test	number	753444071379
Result		✓ Passed
Next expiry date		2024-06-15
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #14	2022-06-10 14:57
MOT test number	207030821531
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge wearing on (5.2.3 (e))	both edges 175/65r15
Advice Nearside Oil leak, but not excessive possible diff seal (8.4.1 (a) (i))	

MOT #13	2022-06-10 08:03		
MOT test number	773566320359		
Result	🗙 Failed		
Advice Nearside Oil leak, but not excessive possible diff seal (8.4.1 (a) (i))			
<b>Fail</b> Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))			
Advice Nearside Front Tyre worn close to legal limit/worn on edge wearing on both edges 175/65r15 (5.2.3 (e))			
<b>Fail</b> Offside Front Coil spring fractured or broken (5.3.1 (b) (i))			





MOT #12		2021-06-16 12:00
MOT test	number	124393313915
Result		🗸 Passed
MOT #11		2020-09-22 15:11
MOT test	number	156544165951
Result		✓ Passed
Advice	Nearside Front Strut top mount bearing slightly rough on rotation	
Advice	Offside Front Strut top mount bearing slightly rough on rotation	

MOT #10		2020-09-22 15:10
MOT test number		808792630997
Result		🗙 Failed
Pass with rectification	Offside Rear Direction indicator incorrect colour (4.4.3 (a))	
Advice Nearside Front S	strut top mount bearing slightly rough on rotation	
Pass with rectification	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))	
Advice Offside Front Str	rut top mount bearing slightly rough on rotation	

MOT #9	2019-09-25 10:24
MOT test number	768333469010
Result	✓ Passed

MOT #8	20	18-09-18 08:25
MOT test num	iber	385470801194
Result		✓ Passed
Advice Fro	ont Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	



Μ	F	6	1	Κ	U	S
re	epo	rt d	ate	: 202	24-0	3-29

MOT #7	2018-09-17 10:06
MOT test number	539609028484
Result	🗙 Failed
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii))	)
Advice Nearside Front Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (	ii))
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))

МОТ #6	2017-09-21 09:29
MOT test number	736890115307
Result	✓ Passed
Advice O/S Rear tyre heavily age cracked but no ply or cord exposed	

MOT #5	2016-09-27 11:54
MOT test number	799769418787
Result	✓ Passed

MOT #4		2016-09-27 11:54
MOT test number		511595139377
Result		🗙 Failed
Pass with rectification	Offside Headlamp aim too high (1.8)	
Pass with rectification	Nearside Headlamp aim too high (1.8)	

MOT #3	2015-09-29 15:12
MOT test number	455173061400
Result	✓ Passed





MOT #2	2	2015-09-24 09:32
MOT te	st number	330644402277
Result		🗙 Failed
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Rear parking (secondary) brakes imbalanced (3.7.B.6b)	
Fail	Offside Headlamp aim too low (1.8)	
Fail	Offside Front coil spring broken (2.4.C.1a)	

MOT #1		2014-10-01 10:07
MOT test	number	238614174235
Result		✓ Passed
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	



Tax & MOT check

✓ Taxed Tax due: 1 January 2025	✓ MOT Expires: 15 June 2024
Tax status	Valid until 1 January
Days left	247
MOT expiry date	15 June 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

#### Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





### Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
***********	
********	
*******	
**********	
********	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-09-30
Last registration	2023-06-05
Complete history	See info



Registration #1	2011-09-30	27 mi
Registration #2	2014-10-01	13.931 mi
Registration #3	2015-09-24	15.571 mi
Registration #4	2015-09-29	15.572 mi
Registration #5	2016-09-27	18.305 mi
Registration #6	2016-09-27	18.305 mi
Registration #7	2017-09-21	19.454 mi
Registration #8	2018-09-17	20.444 mi
Registration #9	2018-09-18	20.444 mi
Registration #10		11.777 est
Registration #11		11.777 est
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		





#### Car features

S0225	Air conditioning
S0295	
S0482	
\$0501	
\$0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg
Additional information	
Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	6290534