



report date: 2024-03-29

General information

| | |
|---------------------|-----------------|
| Make | MINI |
| Model | ROADSTER COOPER |
| Colour | Red |
| Year of manufacture | 2013 |
| Top speed | 124 mph |
| 0 - 60 mph | 9.2 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 122 BHP |
| Max. torque | 160 Nm at 4.250 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 39.2 mpg |
| Consumption extra urban | 57.6 mpg |
| Consumption combined | 49.6 mpg |
| CO2 emission | 133 g/km |
| CO2 label | E |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-01 |
| Pictures | 70 |
| Listing price | View report |



source: yesauto.com



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-11-08 |
| MOT pass rate | 100 % |
| MOT passed | 8 |
| Failed MOT tests | 0 |
| Total advice items | 7 |
| Total items failed | 0 |

| | |
|------------------|---|
| MOT #8 | 2023-10-30 10:30 |
| MOT test number | 777854087366 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-08 |
| Advice | Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d)) |
| Minor | Nearside Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i)) |

| | |
|-----------------|--|
| MOT #7 | 2022-10-26 10:56 |
| MOT test number | 118394883256 |
| Result | ✓ Passed |
| Advice | Offside Front Shock absorbers has light misting of oil (5.3.2 (b)) |
| Advice | Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d)) |

| | |
|-----------------|------------------|
| MOT #6 | 2021-11-09 08:56 |
| MOT test number | 716934068884 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #5 | 2020-11-23 13:56 |
| MOT test number | 136525776338 |
| Result | ✓ Passed |



| | |
|---------------|------------------|
| MOT #4 | 2019-12-07 10:07 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 654882515893 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #3 | 2018-12-13 11:26 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 158155769065 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #2 | 2017-12-09 14:24 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 866416375480 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|--|
| Advice | Nearside Rear Tyre worn close to the legal limit @ 2mm (4.1.E.1) |
|---------------|--|

| | |
|---------------|------------------|
| MOT #1 | 2016-12-03 11:53 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 282087948150 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|--|
| Advice | Offside Front Tyre worn close to the legal limit 2-3mm worn very low on outer edge (4.1.E.1) |
|---------------|--|

| | |
|---------------|---|
| Advice | Nearside Front Tyre worn close to the legal limit 2-3mm worn bold on outer edge (4.1.E.1) |
|---------------|---|



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
8 November 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 May |
| Days left | 367 |
| MOT expiry date | 8 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

| | |
|----------|--|
| Damage 1 | |
| Date | |
| Category | |
| Type | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this MINI had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | VE63EKR |
| Plate since | 2019-09-29 |
| Current registration | VE63EKR |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 10 |
| First mileage registration | 2013-12-23 |
| Last registration | 2023-10-30 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2013-12-23 | 27 mi |
| Registration #2 | 2016-12-03 | 15.018 mi |
| Registration #3 | 2017-12-09 | 20.206 mi |
| Registration #4 | 2018-12-13 | 23.921 mi |
| Registration #5 | 2019-12-07 | 25.982 mi |
| Registration #6 | 2020-12-01 | 26.277 mi |
| Registration #7 | 2021-12-01 | 26.277 mi |
| Registration #8 | 2022-12-01 | 26.277 mi |
| Registration #9 | 2023-12-01 | 26.277 mi |
| Registration #10 | 2023-10-30 | 26.277 mi |

More info >



Car features

The MINI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1892 mm |
| Height | 1384 mm |
| Length | 3728 mm |
| Wheel base | 2467 mm |
| Kerb weight | 1120 kg |
| Max. allowed weight | 1410 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 40 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of seats | 2 |

| | |
|---------------|----------|
| Engine number | A437J422 |
|---------------|----------|