





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	AMAROK DC TDI HIGHLINE 4MOTION
Colour	Grey
Year of manufacture	2015
Top speed	108 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	180 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	38.2 mpg
Consumption combined	35.3 mpg
CO2 emission	211 g/km
CO2 label	K



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 2

Date 2022-04-18

Pictures 28

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-11-18
Pictures	21

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

✓ Passed

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

Result

MOT expiry date	2025-01-10
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	8
Total items failed	2

MOT #9	2024-01-02 15:37
MOT test number	765078925180
Result	✓ Passed
Next expiry date	2025-01-10

MOT #8	2023-01-11 11:58
MOT test number	142156686584
Result	✓ Passed

MOT #7		2023-01-04 09:23
MOT test	number	490926720740
Result		🗙 Failed
MAJOR	Nearside Rear Brakes imbalanced across an axle slow coming on (1.2.1 (b) (i))	

MOT #6	2022-01-07 16:22
MOT test number	477577824290

DANGEROUS Steering rack has relative movement to chassis/bodywork (2.1.2 (a) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear half shaft slight weaping of oil

MOT #4 2021-09-21 07:58 **MOT** test number 930582870855 Result × Failed Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Rear half shaft slight weaping of oil Advice **Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Pass with rectification Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #3	2020-09-11 13:00
MOT test number	692873069222
Result	✓ Passed

MOT #2	2019-10-12 10:41
MOT test number	664213337830
Result	✓ Passed


MOT #1	2018-04-19 10:20
MOT test number	712724486814
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 May
Days left	2
MOT expiry date	10 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11




report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

More info >

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	

CarCheck.co.uk page 8/11



GL150TH report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-05-15
Last registration	2024-01-02
Complete history	See info



Registration #1	2015-05-15	29 mi
Registration #2	2018-04-19	32.113 mi
Registration #3	2019-10-12	48.372 mi
Registration #4	2020-09-11	57.735 mi
Registration #5	2021-09-21	73.327 mi
Registration #6	2021-09-21	73.327 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.177 au

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Adult	86%
Children	64%
Pedestrian	47%
Safety systems	57%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	2228 mm
Height	1834 mm
Length	5254 mm
Wheel base	3000 mm
Kerb weight	2093 kg
Max. allowed weight	3170 kg

Additional information

Fuel delivery	Direct Injection
Number of seats	5
Number of axles	2
CarChock co.uk	nago 11/1°

CarCheck.co.uk page 11/11

Engine number

CSHA106152