





General information

Make	BMW
Model	МЗ
Colour	White
Year of manufacture	2011
Top speed	155 mph
0 - 60 mph	4.6 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	414 BHP
Max. torque	400 Nm at 3.900 rpm
Engine capacity	3.999 сс
Cylinders	8
Fuel type	Petrol
Consumption city	17.8 mpg
Consumption extra urban	33.2 mpg
Consumption combined	25.2 mpg
CO2 emission	263 g/km
CO2 label	Μ







Internet history

Date Pictures 2021-07-16

6

Listing price

View report









source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-24
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	25
Total items failed	1

MOT #12	2021-01-20 10:09	
MOT test number	873121723187	
Result	✓ Passed	
Next expiry date	2022-01-19	
Advice Offside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		

MOT #11		2019-07-16 15:10	
MOT test	number	157911180687	
Result		✓ Passed	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2-3mm (5.2.3 (e))		
Advice Nearside Front Tyre slightly damaged/cracking or perishing outer sidewall slight damage (5.2.3 (d) (ii))			
Advice due to sus	Advice Offside Rear slight play felt when shaking wheel top to bottom, unable to verify cause of concern due to suspension layout		
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2-3mm (5.2.3 (e))		





MOT #10		2019-07-16 08:47
MOT test	number	821387807934
Result		🗙 Failed
MAJOR	Front Windscreen washer provides insufficient washer liquid both (3.5 (a))	
Advice due to sus	Offside Rear slight play felt when shaking wheel top to bottom, unable to verify ca spension layout	ause of concern
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2-3mm (5.2.3 (e))	
Minor	Front Headlamp cleaning device inoperative both (4.1.6 (a) (i))	
MAJOR	Offside Rear Service brake excessively binding (1.2.1 (f))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2-3mm (5.2.3 (e))	
Advice (ii))	Nearside Front Tyre slightly damaged/cracking or perishing outer sidewall slight d	amage (5.2.3 (d)
MAJOR	Nearside Rear Service brake excessively binding (1.2.1 (f))	

МОТ #9	2019-03-29 12:46
MOT test number	614074928351
Result	✓ Passed
МОТ #8	2018-11-15 14:36
MOT test number	723930237509
Result	✓ Passed
MOT #7	2018-06-18 11:44
NOT to at mumber	021257674140

MOT test num	ber 831357674	149
Result	V Pas	sed
Advice Eng	gine covers and under trays fitted obscuring some testable items	
Advice Tyre	e worn close to legal limit/worn on edge all four (5.2.3 (e))	
Advice Rea	ar Brake pad(s) wearing thin (1.1.13 (a) (ii))	



NL610A0
report date: 2024-03-28

MOT #6		2017-12-09 15:00
MOT test	number	791518301685
Result		✓ Passed
Advice	Engine cover fitted	
Advice	Under trays fitted	

MOT #5	2016-12-10 11:07
MOT test number	453875544537
Result	🗸 Passed
Advice Lower covers fitted unable to fully inspect some items	

MOT #4	2015-12-10 10:32
MOT test number	268634820962
Result	✓ Passed
Advice Under trays fitted	

МОТ #3	2015-12-08 16:46
MOT test number	238748058573
Result	🗙 Failed
Advice Under trays fitted	
Fail Nearside Front Headlamp not working on dipped beam (1.7.5a)	

MOT #2	2015-08-27 16:47
MOT test number	786985687833
Result	✓ Passed





MOT #1		2014-09-12 10:45
MOT test	number	336705054216
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	N/s front tyre cracking between tread pattern	
Notice	Under-trays fitted obscuring some underside components	
Notice	Rear tyres wearing oninner shoulders	





Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	e et al
Date	*
Category	AMP
Туре	

Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this BMW had different number plates	5.
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-16
Last registration	2021-01-20
Complete history	<u>See info</u>



Registration #1	2011-09-16	7 mi
Registration #2	2014-09-12	18.943 mi
Registration #3	2015-08-27	22.844 mi
Registration #4	2015-12-08	23.473 mi
Registration #5	2015-12-10	23.473 mi
Registration #6	2016-12-10	29.830 mi
Registration #7	2017-12-09	34.908 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Deviaturation #11		
Registration #11		11.777 esi
Registration #11 Registration #12		10.000 est
-		01.000 est 01.000 est 01.000 est





Car features

S0225	Air conditioning
\$0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1804 mm
Height	1424 mm
Length	4615 mm
Wheel base	2761 mm
Kerb weight	1600 kg
Max. allowed weight	2080 kg
Additional information	
Fuel tank capacity	63 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles	2
Engine number	21044858