



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VIVA SL
Colour	White
Year of manufacture	2017
Top speed	106 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	95 Nm at 4.500 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-07-05
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-10
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	14
Total items failed	2

MOT #5	2023-08-10 15:12
MOT test number	741152372745
Result	✓ Passed
Next expiry date	2024-08-10
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing 185/55/15 h (5.2.3 (d) (ii))
Advice	Offside Front Brake pad(s) wearing thin 80% (1.1.13 (a) (ii))
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Brake pad(s) wearing thin 80% (1.1.13 (a) (ii))

**MOT #4** 2023-08-10 10:14**MOT test number** 705566826270**Result** ✗ Failed**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing 185/55/15 h (5.2.3 (d) (ii))**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Front Brake pad(s) wearing thin 80% (1.1.13 (a) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Brake pad(s) wearing thin 80% (1.1.13 (a) (ii))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #3** 2022-08-08 08:43**MOT test number** 737024094547**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #2** 2021-08-11 15:01**MOT test number** 217311001282**Result** ✓ Passed**MOT #1** 2020-09-21 13:54**MOT test number** 530861828663**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
10 August 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	10 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	OV67CUH
Plate since	2019-03-29
Current registration	OV67CUH
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-09-27
Last registration	2023-08-10
Complete history	See info



Registration #1	2017-09-27	6 mi
Registration #2	2020-09-21	20.632 mi
Registration #3		
Registration #4	2021-08-11	22.362 mi
Registration #5		
Registration #6		
Registration #7		

More info >



Safety ratings

NCAP rating	★★★★
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	1876 mm
Height	1485 mm
Length	3675 mm
Wheel base	2385 mm
Kerb weight	864 kg
Max. allowed weight	1353 kg

Additional information

Fuel tank capacity	32 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	L5Q 163080842L5Q