





report date: 2024-03-29

General information

| Make | VOLKSWAGEN |
|---------------------|-------------------------------------|
| Model | TOURAN SE TDI BLUEMOTION TECHNOLOGY |
| Colour | Silver |
| Year of manufacture | 2015 |
| Top speed | 116 mph |
| 0 - 100 km/h | 12.8 seconds |
| 0 - 60 mph | 12.8 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 77 kW / 105 HP / 103 BHP |
|-------------------------|--------------------------|
| Max. torque | 250 Nm at 1.500 rpm |
| Engine capacity | 1.598 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 51.4 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 61.4 mpg |
| CO2 emission | 121 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2022-07-30

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



| MOT | history |
|-------|-----------|
| 1.101 | iliocol y |

| MOT expiry date | 2024-07-21 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 6 |
| Failed MOT tests | 0 |
| Total advice items | 4 |
| Total items failed | 0 |

| MOT #6 | | 2023-07-13 07:54 |
|-----------|--|------------------|
| MOT test | number | 431934281036 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-07-21 |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #5 | 2022-07-22 07:53 |
|-----------------|------------------|
| MOT test number | 460348159109 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2021-08-24 11:11 |
| MOT test number | 505721662921 |
| Result | ✓ Passed |
| | |

| MOT #3 | 2020-08-25 13:34 |
|-----------------|------------------|
| MOT test number | 859355037438 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



MOT #2 2019-05-15 10:27

MOT test number 217450423095

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge close to limit (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge close to limit and worn smooth on inner

edge (5.2.3 (e))

MOT #1 2018-05-22 15:24

MOT test number 152149374222

Result ✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 August |
|------------------|----------------------|
| Days left | 93 |
| MOT expiry date | 21 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

| Date | |
|----------|--|
| Category | |
| Type | |

Damage 2

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| Owner history | |
|--|-------------|
| For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dov here. | |
| ******** | |
| | |
| *************************************** | |
| ******** | |
| | |
| *************************************** | |
| Plate changes | More info > |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | , |
| Current registration | NK. |
| Plate since | |
| Current registration | UK UK |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Control info | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2015-03-31 |
| Last registration | 2023-07-13 |
| Complete history | See info |



| Registration #1 | 2015-03-31 | 21 mi |
|-----------------|------------|------------|
| Registration #2 | 2018-05-22 | 25.608 mi |
| Registration #3 | 2019-05-15 | 31.417 mi |
| Registration #4 | 2020-08-25 | 34.110 mi |
| Registration #5 | | 91.777 esi |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | n.m. |

More info >

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1794 mm |
|---------------------|---------|
| Height | 1674 mm |
| Length | 4397 mm |
| Wheel base | 2678 mm |
| Kerb weight | 1490 kg |
| Max. allowed weight | 2240 kg |

Additional information

| Fuel tank capacity | 60 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| CarChaglegande | no no 11/11 |

CarCheck.co.uk page 11/11

| Number of axles | 2 |
|-----------------|------------|
| Engine number | CAYCAY0859 |