



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 VERVE E4
Colour	Red
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg







LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-07
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #17	2022-01-22 13:31
MOT test number	723255056528
Result	✓ Passed
Next expiry date	2023-02-02

MOT #16	2021-02-03 10:18
MOT test number	877804895792
Result	✓ Passed

Advice Front reg plate small crack, exhaust leak minor front, n/s/f ball joint slight play (ATL), n/s/ outer sill weak, o/s/r tyre wearing on inner wall, o/s/r wheel bearing slight play, n/s/ mirror crack

MOT #15	2019-04-24 14:48
MOT test number	693661184387
Result	✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Play in steering rack inner joint(s) both sides

Minor Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #14	2018-04-25 13:37
MOT test number	108345811900
Result	✓ Passed

Advice Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #13	2017-05-01 09:43
MOT test number	701434459023
Result	✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Sump corroded

Advice Offside Front play in steering rack

**MOT #12**

2016-07-27 14:24

MOT test number

393056498863

Result

✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11**

2015-06-22 14:06

MOT test number

828893475165

Result

✓ Passed

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** N/s/f tyre cracking on inner side wall**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Play in steering rack inner joint(s)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Oil dampness on engine and gearbox

**MOT #10**

2015-06-22 11:46

MOT test number

235263275168

Result**✗ Failed**

- Fail** Nearside Front Main beam 'tell-tale' not working (1.7.4c)
- Notice** N/s/f tyre cracking on inner side wall
- Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Play in steering rack inner joint(s)
- Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Notice** Oil dampness on engine and gearbox
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #9

2014-04-12 11:04

MOT test number

606722004177

Result**✓ Passed**

- Notice** Both rear tyres slightly cracked
- Notice** Play in steering rack inner joint(s)
- Notice** Oil leaking from gearbox area
- Notice** Wipers smearing screen

**MOT #8** 2014-04-12 11:04**MOT test number** 696972304116**Result** ✗ Failed**Notice** Both rear tyres slightly cracked**Notice** Play in steering rack inner joint(s)**Notice** Oil leaking from gearbox area**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Notice** Wipers smearing screen**MOT #7** 2013-04-19 13:35**MOT test number** 447189903155**Result** ✓ Passed**MOT #6** 2013-04-19 13:35**MOT test number** 409119803160**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #5** 2012-04-17 16:06**MOT test number** 667258302133**Result** ✓ Passed**MOT #4** 2012-04-17 11:49**MOT test number** 267378102451**Result** ✗ Failed**Fail** Rear Exhaust system not adequately supported (7.1.1)



MOT #3	2011-04-14 09:50
MOT test number	369754801168
Result	✓ Passed
Notice	Rear wiper split
Advice	Front Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #2	2010-04-22 10:39
MOT test number	114252110115
Result	✓ Passed

MOT #1	2009-04-17 12:56
MOT test number	382137509143
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-03-31
Last registration	2022-01-22
Complete history	See info



Registration #1	2006-03-31	20 mi
Registration #2	2009-04-17	27.034 mi
Registration #3	2010-04-22	36.133 mi
Registration #4	2011-04-14	43.826 mi
Registration #5	2012-04-17	50.280 mi
Registration #6	2012-04-17	50.280 mi
Registration #7	2013-04-19	61.602 mi
Registration #8	2014-04-12	76.218 mi
Registration #9	2015-06-22	87.873 mi
Registration #10	2016-06-22	95.277 mi
Registration #11	2017-06-22	102.681 mi
Registration #12	2018-06-22	110.085 mi
Registration #13	2019-06-22	117.489 mi
Registration #14	2020-06-22	124.893 mi
Registration #15	2021-06-22	132.297 mi
Registration #16	2022-01-22	139.701 mi
Registration #17	2022-01-22	139.701 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	FST65298536