



report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTI S/S ECOFLEX
Colour	White
Year of manufacture	2016
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	126 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-07-03
Pictures	6
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-30
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	20
Total items failed	0

MOT #8	2023-11-14 17:10
MOT test number	643453151262
Result	✓ Passed
Next expiry date	2024-11-30
Advice	Suspension arm pin or bush worn but not resulting in excessive movement both offside and nearside rear [front bushes] (5.3.4 (a) (i))
Advice	Brake disc worn, pitted or scored, but not seriously weakened both fronts (1.1.14 (a) (ii))

MOT #7	2023-11-13 17:24
MOT test number	341234316377
Result	✗ Failed
Advice	Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))
Advice	Brake disc worn, pitted or scored, but not seriously weakened both fronts (1.1.14 (a) (ii))
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
DANGEROUS	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Suspension arm pin or bush worn but not resulting in excessive movement both offside and nearside rear [front bushes] (5.3.4 (a) (i))
Advice	Both front top struts noisy in operation

**MOT #6**

2022-12-01 09:23

MOT test number

899338152244

Result

✓ Passed

Advice Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))**Advice** Both front top strut mountings slightly noisy in operation**Advice** Suspension arm pin or bush worn but not resulting in excessive movement both rear (5.3.4 (a) (i))**Advice** Offside Front tyre slightly wearing on inner tread**MOT #5**

2021-10-13 15:50

MOT test number

755935277426

Result

✓ Passed

Advice Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**MOT #4**

2021-10-11 15:12

MOT test number

803757328847

Result

✗ Failed

Advice Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**MAJOR** Exhaust emissions exceed default limit of 0.7m-1 (8.2.2.2 (b))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #3**

2020-09-18 10:58

MOT test number

805800843086

Result

✓ Passed



MOT #2	2019-07-15 15:06
MOT test number	183345094311
Result	✓ Passed
MOT #1	2018-08-17 11:05
MOT test number	877775422669
Result	✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	SJ65LGW
Plate since	2019-06-29
Current registration	SJ65LGW
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-01-22
Last registration	2023-11-14
Complete history	See info



Registration #1	2016-01-22	10 mi
Registration #2	2018-08-17	21.619 mi
Registration #3	2019-07-15	29.780 mi
Registration #4	2020-09-18	39.260 mi
Registration #5	2022-05-20	55.277 mi
Registration #6	2022-05-20	55.277 mi
Registration #7	2022-05-20	55.277 mi
Registration #8	2022-05-20	55.277 mi
Registration #9	2022-05-20	55.277 mi
Registration #10	2022-05-20	55.277 mi

More info >



Dimensions & weight

Width	2119 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1270 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A20005963088 LN9