



RENAULT

SC630AZ

report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC LL29 SPORT DCI
Colour	Blue
Year of manufacture	2014
Top speed	99 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	42.2 mpg
Consumption combined	37.2 mpg
CO2 emission	190 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-02-21
Pictures	14
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-22
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	8
Total items failed	17

MOT #14	2024-03-23 12:11
MOT test number	801044107470
Result	✓ Passed
Next expiry date	2025-03-22

MOT #13	2023-02-28 16:15
MOT test number	166145561621
Result	✓ Passed
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #12	2023-02-28 16:15
MOT test number	658494668200
Result	✗ Failed
Pass with rectification	Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #11	2022-03-02 15:26
MOT test number	184861133498
Result	✓ Passed

**MOT #10** 2022-03-01 14:58**MOT test number** 818999987839**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #9** 2021-01-25 17:45**MOT test number** 827659136849**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #8** 2021-01-19 21:29**MOT test number** 337140600947**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Front Brake pipe excessively corroded from abs unit to brake flexipipe (1.1.11 (c))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Rear Outer Passenger's seat backrest cannot be secured in the upright position. second row of seats (6.2.6 (a) (i))**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #7** 2020-01-27 18:54**MOT test number** 579535196192**Result** ✓ Passed**Advice** Nearside Front Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #6** 2020-01-27 16:04**MOT test number** 929309227698**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #5** 2019-01-23 10:59**MOT test number** 659730307488**Result** ✓ Passed**MOT #4** 2019-01-18 14:05**MOT test number** 618668104954**Result** ✗ Failed**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Offside Rear Brake pipe excessively corroded from abs valve to the rear flexi pipe (1.1.11 (c))**Fail** Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**Fail** Nearside Rear Brake pipe excessively corroded from abs valve to the rear flexi pipe (1.1.11 (c))**MOT #3** 2018-01-20 12:28**MOT test number** 604161287629**Result** ✓ Passed



MOT #2	2018-01-19 17:08
MOT test number	945250334418
Result	✗ Failed
Fail	Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)
Fail	Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)

MOT #1	2017-01-25 17:12
MOT test number	629657213908
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
27 February 2024

✓

MOT

Expires:
22 March 2025

Tax status	Expired at 27 February 2024
Days left	62 days too late
MOT expiry date	22 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2014-02-17
Last registration	2024-03-23
Complete history	See info



Registration #1	2014-02-17	13 mi
Registration #2	2017-01-25	66.348 mi
Registration #3	2018-01-19	83.376 mi
Registration #4	2018-01-20	83.376 mi
Registration #5	2019-01-18	102.158 mi
Registration #6	2019-01-23	102.160 mi
Registration #7	2020-01-27	119.725 mi
Registration #8	2020-01-27	119.725 mi
Registration #9	2020-01-27	119.725 mi
Registration #10	2020-01-27	119.725 mi
Registration #11	2020-01-27	119.725 mi
Registration #12	2020-01-27	119.725 mi
Registration #13	2020-01-27	119.725 mi
Registration #14	2020-01-27	119.725 mi
Registration #15	2020-01-27	119.725 mi
Registration #16	2020-01-27	119.725 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	58%
Children	79%
Pedestrian	28%
Safety systems	14%
Overall rating	51%
Video	see crash video



Dimensions & weight

Width	1904 mm
Height	1954 mm
Length	5182 mm
Kerb weight	1907 kg
Max. allowed weight	3055 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	9
Number of axles	2

Engine number

C116028