



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 D3 SE
Colour	Blue
Year of manufacture	-
Top speed	137 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Cylinders	5
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	51.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-22
Pictures	11
Listing price	View report



source: yesauto.com

**MOT history**

MOT #10	2022-05-16 10:10
MOT test number	507053322883
Result	✓ Passed
Next expiry date	2023-05-26
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #9	2021-05-27 11:27
MOT test number	561761198626
Result	✓ Passed

MOT #8	2020-03-05 15:52
MOT test number	958709973445
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Engine covers and undertrays fitted obscuring testable items from view of test.

MOT #7	2019-02-27 14:16
MOT test number	495250385689
Result	✓ Passed

MOT #6	2019-02-25 15:09
MOT test number	774876212424
Result	✗ Failed
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))



MOT #5

2018-03-05 13:07

MOT test number

673972176961

Result

✓ Passed

- Advice** Engine cover and Under-Tray cover fitted
- Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Door body seal damaged not Sharpe edge
- Advice** Front Tyre down to 3mm edge worn bold
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front Wipers smearing

MOT #4

2017-03-10 10:07

MOT test number

364111579113

Result

✓ Passed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #3

2016-03-21 14:26

MOT test number

647889299046

Result

✓ Passed

MOT #2

2016-03-21 14:26

MOT test number

137780266477

Result

✗ Failed

- Pass with rectification** Nearside Headlamp not working on main beam (1.7.5a)



MOT #1	2015-03-24 09:58
MOT test number	806803685002
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-03-28
Last registration	2022-05-16
Complete history	See info



Registration #1	2012-03-28	15 mi
Registration #2	2015-03-24	27.535 mi
Registration #3	2016-03-21	48.252 mi
Registration #4	2016-03-21	48.252 mi
Registration #5	2017-03-10	59.900 mi
Registration #6	2018-03-05	68.371 mi
Registration #7	2019-05-20	75.277 mi
Registration #8	2019-05-20	75.277 mi
Registration #9	2019-05-20	75.277 mi
Registration #10	2019-05-20	75.277 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2019-05-20	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2778 mm
Kerb weight	1646 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1137237