





General information

Make	ΤΟΥΟΤΑ
Model	CELICA VVTI RED
Colour	Black
Year of manufacture	2004
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	172 Nm at 4.200 rpm
Engine capacity	1.794 сс
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I








Internet history

Entry 1	
Date	2022-02-10
Pictures	40
Listing price	View report









source: autotrader.co.uk



MOT history

MOT expiry date	2023-01-09
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	33
Total items failed	19

MOT #21	2022-01-10 11:34
MOT test number	795517043157
Result	✓ Passed
Next expiry date	2023-01-09
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice Central Front Oil leak, but not excessive (8.4.1 (a) (i))	

МОТ #20	2020-10-13 15:56
MOT test number	792159372939
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 Minor Offside Registration plate lamp in (i))	. (a) (i)) operative in the case of multiple lamps or light sources (4.7.1 (b)





MOT #19	2020-10-13 12:08
MOT test number	563947336875
Result	🗙 Failed
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light (i))	ht sources (4.7.1 (b)
Fail Nearside Headlamp insecure (4.1.1 (c))	
Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #18		2019-04-16 13:38
MOT test	number	963706515446
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor (i))	Offside Registration plate lamp inoperative in the case of multiple lamps or ligh	nt sources (4.7.1 (b)

МОТ #17	2019-04-16 12:04
MOT test number	213902766468
Result	× Failed
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or (i))	light sources (4.7.1 (b)



MOT #16		2018-04-13 15:57
MOT test	number	484737025585
Result		✓ Passed
Advice	Oil leak	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Nail in tyre	

MOT #15

2017-04-13 16:54

981256210729

🗸 Passed

MOT test number

Result

MOT #3	14	2017-04-12 16:12
MOT te	st number	785758993557
Result		🗙 Failed
Fail	Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Nearside Rear Stop lamp not working (1.2.1b)	
Fail	Nearside Rear Registration plate lamp not working (1.1.C.1d)	
Fail	Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Nearside Front Headlamp aim too low (1.8)	
Fail	Offside Rear Stop lamp not working (1.2.1b)	



RX04KXG
report date: 2024-03-28

MOT #13	2016-04-19 11:12
MOT test number	347639048350
Result	✓ Passed
Advice Offside Rear tyre sidewall cracking	
Advice Rear coil spring corroded nearside and offside (2.4.C.1b)	
MOT #12	2015-04-24 17:04

MOT test number	217684815105
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #11		2015-04-24 17:04
MOT test number		457074915161
Result		🗙 Failed
Advice Offside Rear Tyre v	vorn close to the legal limit (4.1.E.1)	
Advice Nearside Rear Tyre	e worn close to the legal limit (4.1.E.1)	
Advice Rear Brake pad(s)	wearing thin (3.5.1g)	
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)	

MOT #10	2014-04-17 13:06
MOT test number	218137604402
Result	Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	



RX04KXG report date: 2024-03-28

MOT #9		2014-04-17 13:06
MOT test number		245837704459
Result		🗙 Failed
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)	
Advice Front Brake pad	(s) wearing thin (3.5.1g)	

MOT #8	2013-04-10 14:55
MOT test number	569970803186
Result	✓ Passed
MOT #7	2012-04-23 11:39
MOT test number	285134312465
Result	✓ Passed
МОТ #6	2011-04-29 11:19
MOT test number	768820311111

MOT test number	768829311111
Result	✓ Passed

MOT #5		2010-04-17 10:21
MOT test n	umber	313467900142
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Exhaust has part of the system slightly deteriorated (7.1.1a)	
Notice	Some steering and suspension bushes are starting to deteriorate	

MOT #4	2009-04-16 12:23
MOT test number	581526009190
Result	✓ Passed





MOT #3	2008-04-22 15:29
MOT test number	662863918171
Result	✓ Passed
Advice Nearside Front Steering system has slight free play detected at steering w	wheel (2.2.A.1b)
MOT #2	2007-04-07 15:12
MOT test number	100107797486
Result	✓ Passed
MOT #1	2007-04-07 12:08
MOT test number	903017597021
Result	🗙 Failed
Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Offside Front brake disc excessively pitted (3.5.1h)	
Fail Offside Rear brake disc excessively pitted (3.5.1h)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Nearside Front brake disc excessively pitted (3.5.1h)	
Fail Nearside Rear brake disc excessively pitted (3.5.1h)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	ET
Category		LAMP
Туре		
Damage 2		AMPL
	F	A A A A A A A A A A A A A A A A A A A
Date		1º
Category		SMT.
Туре		

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow



RX04KXG report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-04-26
Last registration	2022-01-10
Complete history	See info



Registration #1	2004-04-26	27 mi
Registration #2	2007-04-07	38.681 mi
Registration #3	2007-04-07	38.681 mi
Registration #4	2008-04-22	45.628 mi
Registration #5	2009-04-16	49.804 mi
Registration #6	2010-04-17	54.044 mi
Registration #7	2011-04-29	57.262 mi
Registration #8	2012-04-23	61.892 mi
Registration #9	2013-04-10	64.688 mi
Registration #10	2014-04-17	67.650 mi
Registration #11	2015-04-24	71.376 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 mi
Registration #19		11.777 mi
Registration #20		11.777 est
Registration #21		11.777 mi

More info >





Car features

50225	Air conditionin
\$0295	
50482	
\$0501	
50566	
50567	
50569	

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Kerb weight	1145 kg
Max. allowed weight	1565 kg
Additional information	
Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection

Number of doors	3
Number of seats	4
Engine number	1ZZ1939118