



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO MATCH EDITION TDI
Colour	Black
Year of manufacture	2013
Top speed	105 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	180 Nm at 2.000 rpm
Engine capacity	1.199 cc
Cylinders	3
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	102 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-06
Pictures	5
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-24
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	16
Total items failed	7

MOT #12	2024-02-13 14:31
MOT test number	213912238184
Result	✓ Passed
Next expiry date	2025-02-24
Advice	Offside Front Road wheel slightly distorted Inner rim (5.2.2 (c) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge Wearing on inner edge 185/60/15 (5.2.3 (e))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #11**

2024-02-12 12:27

MOT test number

554321743411

Result

✗ Failed

- Fail** Offside Front Lower Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))
- Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure 185/60/15 (5.2.3 (d) (ii))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Road wheel slightly distorted Inner rim (5.2.2 (c) (i))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Wearing on inner edge 185/60/15 (5.2.3 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #10

2023-02-22 15:12

MOT test number

748217209000

Result

✓ Passed

- Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Nail in tyre
- Advice** Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #9

2022-02-22 15:44

MOT test number

435981673495

Result

✓ Passed

- Advice** Emissions to clean for reading

**MOT #8** 2021-02-25 15:12**MOT test number** 735220424005**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged outer sidewall (5.2.3 (d) (ii))**Advice** Offside Front tyre has slight wear to inner edge**MOT #7** 2020-01-31 10:14**MOT test number** 785492527858**Result** ✓ Passed**Advice** Tyre slightly damaged/cracking or perishing both rear tyres (185/60x15) (5.2.3 (d) (ii))**MOT #6** 2019-01-11 14:25**MOT test number** 663633304624**Result** ✓ Passed**MOT #5** 2019-01-03 11:50**MOT test number** 657099251758**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MOT #4** 2018-05-08 13:28**MOT test number** 747213062248**Result** ✓ Passed**MOT #3** 2017-06-30 12:09**MOT test number** 976410627026**Result** ✓ Passed



MOT #2	2016-07-07 13:28
MOT test number	347559682292
Result	✓ Passed

MOT #1	2016-07-05 14:51
MOT test number	353529232163
Result	✗ Failed
<div>Fail</div> Offside Side repeater not working (1.4.A.2c)	



Tax & MOT check

✓
Taxed

Tax due:
1 February 2025

✓
MOT

Expires:
24 February 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	24 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	FR13RNJ
Plate since	2019-06-29
Current registration	FR13RNJ
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-06-24
Last registration	2024-02-13
Complete history	See info



Registration #1	2013-06-24	15 mi
Registration #2	2016-07-05	9.719 mi
Registration #3	2016-07-07	9.719 mi
Registration #4	2017-06-30	15.692 mi
Registration #5	2018-05-08	19.059 mi
Registration #6	2019-01-03	22.929 mi
Registration #7	2019-01-11	23.057 mi
Registration #8	2019-01-11	23.057 mi
Registration #9	2019-01-11	23.057 mi
Registration #10	2019-01-11	23.057 mi
Registration #11	2019-01-11	23.057 mi
Registration #12	2019-01-11	23.057 mi
Registration #13	2019-01-11	23.057 mi
Registration #14	2019-01-11	23.057 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1134 kg
Max. allowed weight	1620 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Engine number	CFWA366345