



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D5 SE S40
Colour	Grey
Year of manufacture	2007
Top speed	137 mph
0 - 60 mph	7.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	178 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.4 mpg
CO2 emission	184 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-02-06
Pictures	5
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT expiry date	2024-09-06
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	19
Total items failed	11

MOT #18 2023-08-30 15:34**MOT test number** 250417403031**Result** Passed**Next expiry date** 2024-09-06**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Emissions to clean for pick up obd/tail no print out given**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bushes Both sides (5.3.4 (a) (i))**Advice** Slight under side corroison all under areas**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #17** 2022-09-07 13:37**MOT test number** 496899295689**Result** Passed**MOT #16** 2021-06-16 14:42**MOT test number** 193371814586**Result** Passed

**MOT #15**

2020-06-29 10:38

MOT test number

444197337514

Result

✗ Failed

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Side repeater not working (4.4.1 (a) (ii))**Fail** Offside Rear Service brake excessively fluctuating (1.2.1 (e))**MOT #14**

2019-08-06 11:18

MOT test number

974803880467

Result

✓ Passed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #13**

2018-08-16 09:32

MOT test number

906821327990

Result

✓ Passed

MOT #12

2017-08-17 11:14

MOT test number

115451839094

Result

✓ Passed

Advice Parking brake effort 16%

**MOT #11** 2017-08-09 09:03**MOT test number** 305673345651**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Parking brake effort 16%**Fail** Nearside Inner Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #10** 2016-07-29 15:28**MOT test number** 926665203519**Result** ✓ Passed**MOT #9** 2016-07-29 09:53**MOT test number** 165322794993**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #8** 2015-07-22 15:30**MOT test number** 516843605219**Result** ✓ Passed**MOT #7** 2015-07-21 15:06**MOT test number** 249402105201**Result** ✗ Failed**Fail** Offside Side repeater not working (1.4.A.2c)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #6** 2014-08-18 13:05**MOT test number** 648780534210**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Front nearside tyre tread worn on inner edge**MOT #5** 2013-09-11 17:46**MOT test number** 315464753459**Result** ✓ Passed**MOT #4** 2012-09-28 16:15**MOT test number** 847392972250**Result** ✓ Passed**MOT #3** 2012-09-28 09:44**MOT test number** 626452772234**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #2** 2011-10-11 16:08**MOT test number** 205224581210**Result** ✓ Passed



MOT #1	2010-10-19 15:07
MOT test number	602122990229
Result	✓ Passed
Notice	Both sides rear stay arm bushs coming unbonded
Notice	Washer bottle cap missing
Notice	Near side front side marker lamp not working



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
6 September 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	6 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-10-31
Last registration	2023-08-30
Complete history	See info



Registration #1	2007-10-31	15 mi
Registration #2	2010-10-19	38.754 mi
Registration #3	2011-10-11	48.727 mi
Registration #4	2012-09-28	57.381 mi
Registration #5	2012-09-28	57.381 mi
Registration #6	2013-09-11	70.762 mi
Registration #7	2014-08-18	86.017 mi
Registration #8	2015-07-21	99.831 mi
Registration #9	2015-07-22	99.831 mi
Registration #10	2016-07-29	112.101 mi
Registration #11	2016-07-29	112.101 mi
Registration #12	2016-07-29	112.101 mi
Registration #13	2016-07-29	112.101 mi
Registration #14	2016-07-29	112.101 mi
Registration #15	2016-07-29	112.101 mi
Registration #16	2016-07-29	112.101 mi
Registration #17	2016-07-29	112.101 mi
Registration #18	2016-07-29	112.101 mi
Registration #19	2016-07-29	112.101 mi
Registration #20	2016-07-29	112.101 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1543 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	516960
---------------	--------