





report date: 2024-03-28

General information

| Make | VAUXHALL |
|---------------------|------------------|
| Model | MERIVA TECH LINE |
| Colour | Silver |
| Year of manufacture | 2014 |
| Top speed | 110 mph |
| 0 - 60 mph | 14.0 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 99 BHP |
|-------------------------|---------------------|
| Max. torque | 130 Nm at 4.000 rpm |
| Engine capacity | 1.398 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 37.2 mpg |
| Consumption extra urban | 56.5 mpg |
| Consumption combined | 47.1 mpg |
| CO2 emission | 140 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/11



LP14ZBC

report date: 2024-03-28

Internet history

Entry 2


| Date | 2023-03-25 |
|------|------------|
| | |

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

| Date | 2021-02-05 |
|---------------|-------------|
| Pictures | 0 |
| Listing price | View report |

source: autoonline.co.uk

CarCheck.co.uk page 2/11



LP14ZBC

report date: 2024-03-28

| Μ | OT | his | tory |
|---|----|-----|------|
| | | | |

| MOT expiry date | 2025-03-20 |
|--------------------|------------|
| MOT pass rate | 89 % |
| MOT passed | 8 |
| Failed MOT tests | 1 |
| Total advice items | 8 |
| Total items failed | 2 |

| MOT #9 | 2024-03-21 10:19 |
|--|------------------|
| MOT test number | 116040469984 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-20 |
| Advice Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii)) | |

| MOT #8 | 2023-03-21 08:47 |
|---|------------------|
| MOT test number | 861948884831 |
| Result | ✓ Passed |
| Advice Offside Front Tyre slightly damaged (5.2.3 (d) (ii)) | |

| MOT #7 | 2022-06-11 08:12 |
|-----------------|------------------|
| MOT test number | 746967825802 |
| Result | ✓ Passed |

| MOT #6 | 2021-06-22 08:13 |
|-----------------|------------------|
| MOT test number | 879486059303 |
| Result | ✓ Passed |

| MOT #5 | 2020-06-24 12:30 |
|-----------------|------------------|
| MOT test number | 200782369234 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



MOT #4 2019-06-07 11:23

MOT test number 240473631981

MOT #3 2018-06-12 09:58

MOT test number 405977277673

Result Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Central Front Small Exhaust blow on flexible joint

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2018-06-12 09:58

MOT test number 623810353061

Result X Failed

Pass with rectification Offside Front Headlamp aim too low (4.1.2 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Central Front Small Exhaust blow on flexible joint

Pass with rectification Nearside Front Headlamp aim too low (4.1.2 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2017-06-13 08:18

MOT test number 443461477385

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 April |
|------------------|---------------------|
| Days left | 337 |
| MOT expiry date | 20 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | Е |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

| Date | |
|----------|--|
| Category | |
| Туре | |

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



LP14ZBC

report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| Owner history | |
|---|-------------|
| For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Download here. | |
| ******** | |
| | |
| *************************************** | |
| ******** | |
| | |
| ************ | |
| | More info > |
| Plate changes | |
| See in this check if this VAUXHALL had different number plates. | |
| Number of plates | , |
| Current registration | NK NK |
| Plate since | |
| Current registration | IK SIN |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 8/11



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 12 |
| First mileage registration | 2014-06-30 |
| Last registration | 2024-03-21 |
| Complete history | See info |



| Registration #1 | 2014-06-30 | 21 mi |
|------------------|------------|-----------|
| Registration #2 | 2017-06-13 | 28.092 mi |
| Registration #3 | 2018-06-12 | 37.118 mi |
| Registration #4 | 2018-06-12 | 37.118 mi |
| Registration #5 | 2019-06-07 | 42.859 mi |
| Registration #6 | 2020-06-24 | 46.137 mi |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 89% |
| Children | 77% |
| Pedestrian | 55% |
| Safety systems | 86% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| Width | 1994 mm |
|---------------------|---------|
| Height | 1615 mm |
| Length | 4300 mm |
| Wheel base | 2644 mm |
| Kerb weight | 1376 kg |
| Max. allowed weight | 1905 kg |

Additional information

| Fuel tank capacity | 54 |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | B14XER -19EF8057LDD |

CarCheck.co.uk page 11/11