





report date: 2024-03-28

General information

Make	VOLVO
Model	XC60 D4 MOMENTUM AWD
Colour	Red
Year of manufacture	2018
Top speed	127 mph
0 - 60 mph	8.3 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption combined	2.8 mpg
CO2 emission	144 g/km
CO2 label	F



CarCheck.co.uk page 1/10



report date: 2024-03-28

Internet history

Entry 3

Date 2022-01-05

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 2

Date	2021-10-22	
------	------------	--

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-10-22
Pictures	0

Listing price <u>View report</u>

source: heycar.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-06-02
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	4
Total items failed	1

MOT #4	2023-06-03 08:37
MOT test number	907555264474
Result	✓ Passed
Next expiry date	2024-06-02
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3	2022-05-25 15:45
MOT test number	811641896817
Result	✓ Passed

MOI #2	2022-05-25 15:45
MOT test number	742440436068
Result	★ Failed
Pass with rectification	Offside Rear Tyre has a bulge, caused by separation or partial failure of its

Pass with rectification

Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #1		2021-09-14 10:14
MOT test	number	721060641744
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/10



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	2 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 4/10



report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



GN68HTC report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
HARMAN CO. C.	

THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Wombers of states	
Municipal of pratein	
Current registration	OK SIN
Plate since	
Current registration	OK SIL
Plate since	
	More info >

CarCheck.co.uk page 7/10



report date: 2024-03-28

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-09-26
Last registration	2023-06-03
Complete history	See info



Registration #1	2018-09-26	18 mi
Registration #2	2021-09-14	49.197 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.117 es

More info >

CarCheck.co.uk page 9/10




report date: 2024-03-28

Car features

S0225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	98%
Children	87%
Pedestrian	76%
Safety systems	95%
Overall rating	90%
Video	see crash video



Dimensions & weight

Width	1999 mm
Height	1658 mm
Length	4688 mm
Wheel base	2865 mm
Kerb weight	1837 kg
Max. allowed weight	2450 kg

Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 10	0/10

Number of axles 2

Engine number 2839783