





### General information

Make	HONDA
Model	ACCORD VTEC EX
Colour	Silver
Year of manufacture	2007
Top speed	134 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	153 BHP
Max. torque	190 Nm at 4.500 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.2 mpg
Consumption extra urban	44.8 mpg
Consumption combined	33.6 mpg
CO2 emission	200 g/km
CO2 label	J





# Internet history

Entry 1

Date Pictures 2022-06-07

14

Listing price

View report



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-12-03
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	9
Total items failed	14

MOT #21	2023-12-01 14:38
MOT test number	139644144738
Result	✓ Passed
Next expiry date	2024-12-03

MOT #20	2023-12-01 14:38
MOT test number	607261833606
Result	× Failed
Pass with rectification	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer

prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #19	2022-12-04 14:23
MOT test number	100499559431
Result	✓ Passed
Advice Offside Front Upper Suspension arm ball joint has slight play might worsen (5.3.4 (a) (i))	
Minor Offside Outer Drive shaft joint	constant velocity boot severely deteriorated (6.1.7 (g) (i))





MOT #18	2022-12-04 14:23	
MOT test number	162577908102	
Result	× Failed	
Advice Offside Front Up	per Suspension arm ball joint has slight play might worsen (5.3.4 (a) (i))	
Minor Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))		
Pass with rectification	Nearside Rear Seat belt buckle not functioning as intended (7.1.2 (d))	
Pass with rectification	Offside Rear fog lamp not working (4.5.1 (a) (ii))	

MOT #17		2021-12-03 14:49
MOT test	number	521236753280
Result		✓ Passed
Advice	Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))	
		2020 11 10 15 20

MOT #16	2020-11-18 15:20
MOT test number	348136753389
Result	✓ Passed





MOT #15		2020-11-18 09:03
MOT test	number	707557450495
Result		🗙 Failed
Fail	Offside Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail	Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
<b>Fail</b> (ii))	Offside Lower Suspension arm ball joint dust cover no longer prevents the ingre	ss of dirt (5.3.4 (b)
Fail	Nearside Front Electrical wiring insecure and in contact with sharp edges (4.11 (	(a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail	learside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
<b>Fail</b> (5.2.3 (d)	Offside Front Tyre has a cut in excess of the requirements deep enough to reacl (i))	n the ply or cords
<b>Fail</b> (2.1.3 (g)	learside Track rod end ball joint dust cover insecure so that it no longer preven (ii))	ts the ingress of dirt
Fail	learside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #14	2019-05-24 09:33
MOT test number	849560877969
Result	✓ Passed
MOT #13	2018-11-14 15:34
MOT test number	925500494989

Result	✓ Passed
MOT #12	2017-11-15 15:06

MOT test number	807685827256
Result	✓ Passed





MOT #11	2017-11-15 13:42
MOT test number	882349372808
Result	🗙 Failed
<b>Fail</b> Offside Rear Brake pad(s) less than 1.5 mm thick inner pad (3.5.1g)	
MOT #10	2016-11-30 14:09
MOT test number	777872746049
Result	🗸 Passed
MOT #9	2015-12-08 14:27
MOT test number	229427706805
Result	✓ Passed
Advice Nearside Rear nail in tyre	
MOT #8	2014-12-12 13:20
MOT test number	169166544336
Result	🗸 Passed
MOT #7	2013-12-31 11:05
MOT test number	587645263398
Result	✓ Passed
MOT #6	2012-12-10 16:24
MOT test number	957135142337
Result	✓ Passed
MOT #5	2012-12-10 15:44
MOT test number	748105142390
Result	🗙 Failed
Fail         Nearside Front Anti-roll bar linkage insecure (2.4.G.1)	





MOT #4	2011-11-22 09:26
MOT test number	367896121397
Result	Passed
MOT #3	2011-11-21 13:36
MOT test number	495045021486
Result	🗙 Failed
<b>Fail</b> Offside Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)	
MOT #2	2010-12-21 15:31
MOT test number	732375950351
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2010-02-25 16:10
MOT test number	451816150072
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 December 2024	✓ MOT Expires: 3 December 2024
Tax status	Valid until 1 December
Days left	216
MOT expiry date	3 December 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

#### Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





# Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
************	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-03-01
Last registration	2023-12-01
Complete history	<u>See info</u>



Registration #1	2007-03-01	29 mi
Registration #2	2010-02-25	11.395 mi
Registration #3	2010-12-21	15.410 mi
Registration #4	2011-11-21	18.925 mi
Registration #5	2011-11-22	18.925 mi
Registration #6	2012-12-10	23.104 mi
Registration #7	2012-12-10	23.104 mi
Registration #8	2013-12-31	26.635 mi
Registration #9	2014-12-12	30.426 mi
Registration #10	2015-12-08	33.684 mi
Registration #11	2016-11-30	36.911 mi
Registration #12	2017-11-15	39.195 mi
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 esi
Registration #18		11.777 est
Registration #19		11.777 esi
Registration #20		11.777 est
Registration #21		11.777 esi
Registration #22		11.117 est
Registration #23		11.777 esi

More info >





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1760 mm
Height	1445 mm
Length	4665 mm
Wheel base	2670 mm
Max. allowed weight	1920 kg
Additional information	
Additional information Fuel tank capacity	65 l
	65 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 4