



PEUGEOT




report date: 2024-03-29

General information

Make	PEUGEOT
Model	508 HDI SW ACTIVE NAVIGATION VERSION
Colour	Grey
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	240 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-07-30
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



## MOT history

MOT expiry date	2024-11-15
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	24
Total items failed	10

MOT #14	2023-11-08 12:11
MOT test number	554087354711
Result	✓ Passed
Next expiry date	2024-11-15

MOT #13	2022-11-16 09:45
MOT test number	226387592271
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Slight imbalance on front brakes
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2021-08-13 09:11
MOT test number	762340889555
Result	✓ Passed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Front Tyre worn close to legal limit/worn on edge both tyres outer edges (5.2.3 (e))

**MOT #11**

2021-08-11 13:06

**MOT test number**

549653585826

**Result****✗ Failed**

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge both tyres outer edges (5.2.3 (e))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Windscreen washer not working (3.5 (a))

**MOT #10**

2020-11-25 10:39

**MOT test number**

279544665839

**Result****✓ Passed**

- Advice** Offside Front Anti-roll bar ball joint has slight play link-bar end (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin with discs worn thin and lipped (1.1.13 (a) (ii))

**MOT #9**

2019-11-29 14:55

**MOT test number**

417928671731

**Result****✓ Passed**

- Advice** Front Brake disc worn, but not excessively vented brake discs worn to minimum thickness (1.1.14 (a) (i))
- Advice** Offside Front Anti-roll bar ball joint has slight play link-bar (5.3.4 (a) (i))

**MOT #8** 2019-11-29 09:26**MOT test number** 405405780540**Result** ✗ Failed**Advice** Offside Front Anti-roll bar ball joint has slight play link-bar (5.3.4 (a) (i))**Advice** Front Brake disc worn, but not excessively vented brake discs worn to minimum thickness (1.1.14 (a) (i))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #7** 2018-11-26 10:48**MOT test number** 887495467897**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))**Advice** Screen washer reservoir leaking**MOT #6** 2018-11-26 10:48**MOT test number** 207110777688**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))**Advice** Screen washer reservoir leaking**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #5** 2017-11-09 07:43**MOT test number** 195984355270**Result** ✓ Passed**MOT #4** 2016-11-30 08:10**MOT test number** 272050883863**Result** ✓ Passed

**MOT #3** 2016-11-28 15:09**MOT test number** 714214749739**Result** ✗ Failed**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Nail in tyre**MOT #2** 2016-04-28 10:57**MOT test number** 556682874326**Result** ✓ Passed**Advice** Vehicle has under body protection...some items obscured.**MOT #1** 2016-04-26 13:49**MOT test number** 540501538847**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin pad material getting low. (3.5.1g)**Advice** Vehicle has under body protection...some items obscured.**Pass with rectification** Offside Headlamp aim too far to the right (1.8)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Pass with rectification** Nearside Headlamp aim too high (1.8)**Fail** Offside Front Outer Brake pad(s) less than 1.5 mm thick pad material very low and backing just off disc. (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
15 November 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	15 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-04-24
Last registration	2023-11-08
Complete history	<a href="#">See info</a>



Registration #1	2013-04-24	12 mi
Registration #2	2016-04-26	39.583 mi
Registration #3	2016-04-28	39.663 mi
Registration #4	2016-11-28	47.648 mi
Registration #5	2016-11-30	47.648 mi
Registration #6	2017-11-09	58.642 mi
Registration #7	2018-11-26	69.559 mi
Registration #8	2018-11-26	69.559 mi
Registration #9	2019-11-26	75.277 mi
Registration #10	2019-11-26	75.277 mi
Registration #11	2019-11-26	75.277 mi
Registration #12	2019-11-26	75.277 mi
Registration #13	2019-11-26	75.277 mi
Registration #14	2019-11-26	75.277 mi
Registration #15	2019-11-26	75.277 mi
Registration #16	2019-11-26	75.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	87%
Pedestrian	41%
Safety systems	97%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1853 mm
Height	1476 mm
Length	4813 mm
Wheel base	2817 mm
Kerb weight	1578 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	72 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	JBEU3040389