



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I20 CRDI SE
Colour	Black
Year of manufacture	2017
Top speed	109 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	240 Nm at 2.500 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	80.7 mpg
Consumption combined	68.9 mpg
CO2 emission	102 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-07-14
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-24
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	20
Total items failed	9

MOT #6 2023-09-25 12:56

MOT test number 730752963798

Result ✓ Passed

Next expiry date 2024-09-24

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

Minor Offside Obligatory mirror slightly damaged wing mirror (3.3 (b) (i))

Minor Offside Rear Inner Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Advice Offside Rear light lens slightly damaged

Minor Offside Rear Rear reflector insecure (4.8.1 (b) (i))

Minor Nearside Rear Outer Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #5 2022-07-21 14:51

MOT test number 899129405179

Result ✓ Passed

MOT #4 2021-07-02 13:42

MOT test number 409995209863

Result ✓ Passed

**MOT #3**

2021-06-23 13:17

MOT test number

616125678538

Result**✗ Failed****Fail**

Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail

Nearside Rear Tyre has ply or cords exposed cut in tread (5.2.3 (d) (ii))

Fail

Offside Body panel damaged and likely to cause injury mirror casing (6.2.1 (a) (i))

Advice

Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #2

2020-10-08 12:45

MOT test number

357848006261

Result**✓ Passed****Minor**

Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

Advice

Stone chip in windscreen

Advice

Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice

Offside body panels damaged



MOT #1

2020-10-01 11:04

MOT test number

934771116104

Result		✗ Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice	Stone chip in windscreen	
Fail	Offside Rear Parking brake inoperative on one side 104 (1.4.1 (a))	
Fail	Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))	
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor	Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))	
Fail	Nearside Rear Parking brake inoperative on one side 46 (1.4.1 (a))	
Advice	Offside body panels damaged	
Fail	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))	
Fail	Offside Rear Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1 (b) (ii))	



Tax & MOT check

×

Untaxed

Tax expired:
1 July 2023

✓

MOT

Expires:
24 September 2024

Tax status	Expired at 1 July 2023
Days left	302 days too late
MOT expiry date	24 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	 BN67AUE
Plate since	2024-03-29
Current registration	 BN67AUE
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-01
Last registration	2023-09-25
Complete history	See info



Registration #1	2017-09-01	6 mi
Registration #2	2020-10-01	117.530 mi
Registration #3	2020-10-08	117.742 mi
Registration #4	2021-06-23	120.735 mi
Registration #5	2022-09-25	121.277 mi
Registration #6	2023-09-25	121.277 mi
Registration #7	2023-09-25	121.277 mi
Registration #8	2023-09-25	121.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	85%
Children	73%
Pedestrian	79%
Safety systems	64%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1734 mm
Height	1474 mm
Length	4035 mm
Wheel base	2570 mm
Kerb weight	1280 kg
Max. allowed weight	1690 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FCGU668746