



report date: 2024-03-29

General information

| | |
|---------------------|------------------|
| Make | VOLVO |
| Model | XC60 D3 DRIVE ES |
| Colour | Black |
| Year of manufacture | 2012 |
| Top speed | 124 mph |
| 0 - 60 mph | 10.0 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 161 BHP |
| Max. torque | 400 Nm at 1.400 rpm |
| Engine capacity | 1.984 cc |
| Cylinders | 5 |
| Fuel type | Diesel |
| Consumption city | 37.7 mpg |
| Consumption extra urban | 57.7 mpg |
| Consumption combined | 47.9 mpg |
| CO2 emission | 149 g/km |
| CO2 label | F |





Internet history

Entry 3

| | |
|---------------|-----------------------------|
| Date | 2021-09-04 |
| Pictures | 5 |
| Listing price | View report |



source: cargurus.co.uk

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-09-03 |
| Pictures | 5 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-31 |
| MOT pass rate | 80 % |
| MOT passed | 8 |
| Failed MOT tests | 2 |
| Total advice items | 11 |
| Total items failed | 5 |

| | |
|------------------|------------------|
| MOT #10 | 2023-10-31 12:45 |
| MOT test number | 107970969701 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-31 |

| | |
|-----------------|--|
| MOT #9 | 2022-11-01 13:18 |
| MOT test number | 691864075228 |
| Result | ✓ Passed |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice | Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Front Outer Tyre slightly damaged (5.2.3 (d) (ii)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge 1.6mm (5.2.3 (e)) |

| | |
|-----------------|------------------|
| MOT #8 | 2021-11-01 14:55 |
| MOT test number | 919100254656 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #7 | 2021-03-25 08:06 |
| MOT test number | 586699693384 |
| Result | ✓ Passed |

**MOT #6** 2019-11-23 14:56**MOT test number** 759886182873**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #5** 2019-11-22 15:56**MOT test number** 609112957882**Result** ✗ Failed**Fail** Offside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Headlamp aim not tested (4.1.2 (b))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #4** 2018-10-29 16:49**MOT test number** 793333605126**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**MOT #3** 2017-10-30 16:30**MOT test number** 751796253430**Result** ✓ Passed**MOT #2** 2016-09-21 16:27**MOT test number** 870918056077**Result** ✓ Passed**Advice** Centre Rear Child Seat fitted not allowing full inspection of adult belt



| | |
|-----------------|--|
| MOT #1 | 2016-09-21 11:22 |
| MOT test number | 154007090075 |
| Result | ✗ Failed |
| Fail | Nearside Stop lamp not working (1.2.1b) |
| Fail | Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) |
| Advice | Centre Rear Child Seat fitted not allowing full inspection of adult belt |



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✓
MOT

Expires:
31 October 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 March |
| Days left | 306 |
| MOT expiry date | 31 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | YD62XHP |
| Plate since | 2024-03-29 |
| Current registration | YD62XHP |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2012-09-10 |
| Last registration | 2023-10-31 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2012-09-10 | 26 mi |
| Registration #2 | 2016-09-21 | 39.553 mi |
| Registration #3 | 2016-09-21 | 39.553 mi |
| Registration #4 | 2017-10-30 | 49.674 mi |
| Registration #5 | 2018-10-29 | 57.343 mi |
| Registration #6 | 2019-11-22 | 66.338 mi |
| Registration #7 | 2019-11-23 | 66.338 mi |
| Registration #8 | 2019-11-23 | 66.338 mi |
| Registration #9 | 2019-11-23 | 66.338 mi |
| Registration #10 | 2019-11-23 | 66.338 mi |
| Registration #11 | 2019-11-23 | 66.338 mi |
| Registration #12 | 2019-11-23 | 66.338 mi |
| Registration #13 | 2019-11-23 | 66.338 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 94% |
| Children | 79% |
| Pedestrian | 48% |
| Safety systems | 86% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1891 mm |
| Height | 1713 mm |
| Length | 4627 mm |
| Wheel base | 2774 mm |
| Kerb weight | 1756 kg |
| Max. allowed weight | 2505 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 1161516 |