





report date: 2024-03-28

### General information

Make	FORD
Model	KUGA TITANIUM X SPORT TDCI
Colour	Black
Year of manufacture	2015
Top speed	121 mph
0 - 100 km/h	12.0 seconds
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	370 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	122 g/km
CO2 label	D



CarCheck.co.uk page 1/11



### Internet history

### Entry 1

Date 2021-06-10

Pictures 51

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-07-10
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	10
Total items failed	4

MOT #7	2023-07-11 12:56
MOT test number	191308755230
Result	✓ Passed
Next expiry date	2024-07-10
Advice Exhaust rear silencer cracked	

MOT #6	2022-07-05 09:31
MOT test number	654454083986
Result	<b>✓</b> Passed
Advice Passenger front wiper blade deteriorating and slightly smears	

MOT #5		2021-07-08 15:52
MOT test	number	242588441767
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))		
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/11



**Advice** 

EA65JKJ report date: 2024-03-28

**MOT #4** 2021-07-07 08:42 **MOT** test number 414601102755 Result × Failed Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Fail Offside Front Position lamp not working (4.2.1 (a) (ii)) Pass with rectification Front Windscreen washer provides insufficient washer liquid both sides (3.5 (a)) **Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Oil leak, but not excessive (8.4.1 (a) (i))

**MOT** #3 2020-09-18 15:19 **MOT** test number 736130349860 Result ✓ Passed **MOT #2** 2019-09-17 09:23 **MOT** test number 938668928119 Result ✓ Passed **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #1
 2018-09-20 05:46

 MOT test number
 596126799857

 Result
 ✓ Passed

CarCheck.co.uk page 4/11



### Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	10 July 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report <u>k</u>	
*********	
***************************************	
************	
**********	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
See in this check if this FOND had different humber plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK SILV
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



### Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-10-30
Last registration	2023-07-11
Complete history	See info



Registration #1	2015-10-30	25 mi
Registration #2	2018-09-20	43.327 mi
Registration #3	2019-09-17	57.065 mi
Registration #4	2020-09-18	68.502 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Adult	94%
Children	86%
Pedestrian	70%
Safety systems	100%
Overall rating	88%
Video	see crash video



## Dimensions & weight

Width	2077 mm
Height	1689 mm
Length	4524 mm
Wheel base	2690 mm
Kerb weight	1614 kg
Max. allowed weight	2250 kg

# Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 11	/11

Number of axles2Engine numberFJ81656